

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

(Continued)

EDR ID Number
EPA ID Number

Database(s)

S105390070

WA SPILL:

Facility ID: 506008
Date Received: 08/13/1999
Business Name: UNITED PARCEL SERVICE
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: ROADWAY-PAVED
Material Qty: 50
Material Units: GALLON

BR302
SSW
1/2-1
4327 ft.
Higher

1050 SOUTH 96TH ST SEATTLE
SEATTLE, WA

SPILLS S105387178
N/A

Site 1 of 2 in cluster BR

WA SPILL:

Facility ID: 502539
Date Received: 10/05/1998
Business Name: CONTRACTOR
Material Desc : OTHER HAZARDOUS
Medium: SOIL
Material Qty: Not reported
Material Units: Not reported

BR303
SSW
1/2-1
4327 ft.
Higher

BARCO
1050 S. 96TH ST.
SEATTLE, WA 98108

WA ICR S104485316
N/A

Site 2 of 2 in cluster BR

WA ICR:

Date Ecology Received Report: 10/05/1998
Contaminants Found at Site: Metals
Petroleum products
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-12
County Code: 17
Contact: Not reported
Report Title: Not reported

BN304
SSW
1/2-1
4338 ft.
Higher

MARKEY PROPERTY PARCEL 4
PARCEL 4 S 96TH ST 10TH AVE S
SEATTLE, WA 98108

CSCSL NFA S100079834
N/A

Site 6 of 6 in cluster BN

WA NFA:

Facility/Site Id : 2263
Ecology Status : Independent Remedial Action
Independent Status Code : Not reported
WARM Bin Number : 3
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 8/10/2001 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site Database(s) EDR ID Number
EPA ID Number

305 ETT:X-RAY, INC.
NE 7500 PERIMETER RD., S.
1/2-1 SEATTLE, WA 98108
4349 ft.
Higher

MLTS 1000976979
N/A

MLTS:

License Number: SNM-1899 First License Date: 07/19/1982
License Date: 03/05/2002 Institution Code: 19517
License Expires: 07/31/2003 Primary Program: Medical Private Practice - Limited
License Use: SNM Plutonium - Neutron Sources Less Than 200 Grams
Department: Not reported Building: Not reported
Contact Name: DONALD H. SEBASTIAN, V.P. Contact Phone: 201-645-5297
States Allowing Use: Not reported
Store Material: No
Redistribution: No Incineration: No
Burial: No
Last Inspection: 01/2002
Inspector Name: S. LODHI
Next Inspection: 01/2003

306 NORTHWEST CONTAINER SVCS INC SEATTLE
NW 600 S GARDEN ST
1/2-1 SEATTLE, WA 98108
4351 ft.
Lower

RCRIS-SQG 1001490949
FINDS WAD988517744

RCRIS:

Owner: TED SAND
(360) 555-1212
EPA ID: WAD988517744
Contact: DOUG NIXON
(425) 702-1007
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
PCB Handler Activity Data System (PADS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BS307 SEA PAC RESOURCES INC
ENE 8465 PERIMETER RD S
1/2-1 SEATTLE, WA 98108
4353 ft.
Higher
Site 1 of 2 in cluster BS

RCRIS-SQG 1000139469
FINDS WAD980985832

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SEA PAC RESOURCES INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000139469

RCRIS:

Owner: SEA PAC RESOURCES INC
(360) 555-1212
EPA ID: WAD980985832
Contact: JOHN LAXDAL
(206) 767-0501

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

308
SSW
1/2-1
4366 ft.
Higher

SCD PROPERTY
1000 S. 96TH
SEATTLE, WA 98108

WA ICR S105225205
N/A

WA ICR:

Date Ecology Received Report: 01/09/2002
Contaminants Found at Site: Metals
44
Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-45
County Code: 17
Contact: Not reported
Report Title: Second Water Quality Monitoring- December 2001

309
NE
1/2-1
4374 ft.
Higher

FEDEX BFI VM
7440 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG 1001490648
FINDS WAD988483558

RCRIS:

Owner: FEDERAL EXPRESS CORP
(800) 463-3339
EPA ID: WAD988483558
Contact: Haz-Waste Mgr
(253) 735-2292

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FEDEX BFI VM (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001490648

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BS310
ENE
1/2-1
4376 ft.
Higher

SEATTLE AIR CORP
8535 PERIMETER RD S
SEATTLE, WA 98101

UST **U003311148**
WA ICR **N/A**
LUST

Site 2 of 2 in cluster BS

LUST:

Facility ID: 447641 Ecology Region: North Western
Release ID: 510248 Release Date: 8/26/1996 00:00:00
Release Status: Cleanup Started Status Date: 7/16/1996 00:00:00
Alternate Name: SEATTLE AIR CORP
Affected Media: Soil

Facility ID: 447641 Ecology Region: North Western
Release ID: 510248 Release Date: 8/26/1996 00:00:00
Release Status: Reported Cleaned Up Status Date: 8/26/1996 00:00:00
Alternate Name: SEATTLE AIR CORP
Affected Media: Soil

WA ICR:

Date Ecology Received Report: 08/26/1996
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-17
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 447641
Install Date: Not reported
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: MOTOR OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BT311
NNW
1/2-1
4387 ft.
Lower

COLOUR SYSTEMS INTL LLC
1017 S MYRTLE ST
SEATTLE, WA 98108

FINDS **1004991409**
000007565348

Site 1 of 6 in cluster BT

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

COLOUR SYSTEMS INTL LLC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004991409

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

BT312
NNW
1/2-1
4387 ft.
Lower

COLOUR SYSTEMS INTL LLC
1017 S MYRTLE ST
SEATTLE, WA 98108

RCRIS-SQG 1001233973
WAH000003780

Site 2 of 6 in cluster BT

RCRIS:

Owner: COLOUR SYSTEMS INTL LLC
(206) 768-1500
EPA ID: WAH000003780
Contact: CHRIS BEALL
(206) 768-1500

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

BT313
NNW
1/2-1
4393 ft.
Lower

SEATTLE CITY LIGHT
1012 S. MYRTLE ST.
SEATTLE, WA 98108

WA ICR S104487381
N/A

Site 3 of 6 in cluster BT

WA ICR:

Date Ecology Received Report: 09/14/1990
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 90-12
County Code: 17
Contact: Not reported
Report Title: Not reported

BT314
NNW
1/2-1
4393 ft.
Lower

SEA.CTY LIGHT MYRTLE ST (EXEMPT)
1012 S MYRTLE ST
SEATTLE, WA 98108

UST U003749941
LUST N/A

Site 4 of 6 in cluster BT

LUST:

Facility ID: 200100 Ecology Region: North Western
Release ID: 2871 Release Date: 9/14/1990 00:00:00
Release Status: Cleanup Started Status Date: 5/21/1995 00:00:00
Alternate Name: SEATTLE CITY LIGHT MYRTLE ST (EXEMPT)
Affected Media: Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SEA.CTY LIGHT MYRTLE ST (EXEMPT) (Continued)

U003749941

Facility ID: 200100 Ecology Region: North Western
Release ID: 2871 Release Date: 9/14/1990 00:00:00
Release Status: Reported Cleaned Up Status Date: 3/6/2001 00:00:00
Alternate Name: SEATTLE CITY LIGHT MYRTLE ST (EXEMPT)
Affected Media: Soil

UST:

Facility ID: 200100
Install Date: Not reported
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BT315
NNW
1/2-1
4408 ft.
Lower

CITY OF SEATTLE - FIRE STATION 2
1000 S. MYRTLE ST.
SEATTLE, WA 98108

WA ICR S104782979
N/A

Site 5 of 6 in cluster BT

WA ICR:

Date Ecology Received Report: 06/29/2000
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-29
County Code: 17
Contact: Not reported
Report Title: UST Site Assessment

BT316
NNW
1/2-1
4408 ft.
Lower

SEATTLE FIRE STATION 27
1000 S MYRTLE ST
SEATTLE, WA 98108

UST U000592332
LUST N/A

Site 6 of 6 in cluster BT

LUST:

Facility ID: 7886 Ecology Region: North Western
Release ID: 549580 Release Date: 6/29/2000 00:00:00
Release Status: Cleanup Started Status Date: 12/10/1999 00:00:00
Alternate Name: SEATTLE CITY OF FIRE STATION # 27
Affected Media: Soil

UST:

Facility ID: 7886
Install Date: 1/1/1971 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

317
SSW
1/2-1
4411 ft.
Higher

TERREL SOMMERS INC
9508 8TH AVE S
SEATTLE, WA 98108

Database(s)	EDR ID Number EPA ID Number
RCRIS-SQG FINDS	1000355559 WAD048685440

RCRIS:

Owner: TERREL SOMMERS INC
(360) 555-1212
EPA ID: WAD048685440
Contact: JOHN KETOLA
(206) 762-4970
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BU318
NE
1/2-1
4417 ft.
Higher

BOEING ELECTRONIC MANUFACTURING FIVE REPORTS)
7355 PERIMETER ROAD S.
SEATTLE, WA 98108

Site 1 of 3 in cluster BU

WA ICR S104484983
N/A

WA ICR:

Date Ecology Received Report: 05/15/1998
Contaminants Found at Site: Solvents
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-04
County Code: 17
Contact: Not reported
Report Title: Not reported

BU319
NE
1/2-1
4417 ft.
Higher

BOEING S&CS ELECTRONIC MFG FACILITY
7355 PERIMETER RD S
SEATTLE, WA 98108

Site 2 of 3 in cluster BU

RCRIS-SQG 1000257103
FINDS WAD980980270
UST
CSCSL

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING S&CS ELECTRONIC MFG FACILITY (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257103

RCRIS:

Owner: BOEING CO
(425) 865-2400
EPA ID: WAD980980270
Contact: THOMAS GALLACHER
(206) 544-2862
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 73142589
Responsible Unit: NW
Latitude: 47 32 17
Longitude: 122 18 19
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Ground Water
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 73142589
Responsible Unit: NW
Latitude: 47 32 17

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING S&CS ELECTRONIC MFG FACILITY (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257103

Longitude: 122 18 19
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Soil
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

UST:

Facility ID: 10416
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10416
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BV320
NW
1/2-1
4444 ft.
Lower
FERGUSON CONSTRUCTION
7433 5TH AVE S
SEATTLE, WA 98108
Site 1 of 4 in cluster BV

WA NFA:

Facility/Site Id : 3565459
Ecology Status : Independent Remedial Action

UST U003665840
CSCSL NFA N/A
WA ICR

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FERGUSON CONSTRUCTION (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003665840

Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assessment IRAP or VCP
NFA Date : 5/29/1996 00:00:00

WA ICR:

Date Ecology Received Report: 09/20/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-04
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/24/1996
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 95-16
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 09/19/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-17
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 200658
Install Date: Not reported
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BU321
NE
1/2-1
4446 ft.
Higher

BOEING ELECTRONIC MFG
7300 PERIMETER RD S
SEATTLE, WA 98108

Site 3 of 3 in cluster BU

SHWS:

Facility ID: 63879778
Responsible Unit: NW
Latitude: 47 32 7
Longitude: 122 18 4

CSCSL S104971190
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING ELECTRONIC MFG (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104971190

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

322
NNW
1/2-1
4449 ft.
Lower

**COASTAL ALASKA MARINE LINES
745 S ORCHARD ST
SEATTLE, WA 98108**

**RCRIS-SQG 1000387900
FINDS WAD980834527**

RCRIS:
Owner: COASTAL ALASKA MARINE LINES
(360) 555-1212
EPA ID: WAD980834527
Contact: CAIN MIC
(206) 767-4401

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

**BW323 SEATTLE CITY SOUTH RECYCLING & DISPOS
WNW 8100 2ND AVE S
1/2-1 SEATTLE, WA 98108
4451 ft.
Lower Site 1 of 3 in cluster BW**

**RCRIS-SQG 1000421907
FINDS WAD980833826
CERC-NFRAP**

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SEATTLE CITY SOUTH RECYCLING & DISPOS (Continued)

1000421907

CERCLIS-NFRAP Classification Data:

Site Incident Category:	Not reported	Federal Facility:	Not a Federal Facility
Non NPL Code:	NFRAP		
Ownership Status:	Other	NPL Status:	Not on the NPL
CERCLIS-NFRAP Assessment History:			
Assessment:	DISCOVERY	Completed:	06/01/1981
Assessment:	PRELIMINARY ASSESSMENT	Completed:	06/10/1985

RCRIS:

Owner: SEATTLE PUBLIC UTILITIES SOLID WASTE
(206) 684-7666
EPA ID: WAD980833826
Contact: JEFF NEUNER
(206) 684-7693

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BW324 CITY OF SEATTLE SOLID WASTE DIV STS
WNW 8100 2ND AVE S
1/2-1 SEATTLE, WA 98108
4451 ft.
Lower Site 2 of 3 in cluster BW

UST U001127483
WA ICR N/A
SPILLS

WA SPILL:

Facility ID: 514042
Date Received: 10/13/2000
Business Name: CITY OF SEATTLE
Material Desc : OTHER HAZARDOUS
Medium: SURFACE WATER-FRESH
Material Qty: Not reported
Material Units: Not reported

WA ICR:

Date Ecology Received Report: 03/18/1993
Contaminants Found at Site: Total petroleum hydrocarbons
Metals
Polynuclear aromatic hydrocarbons
Media Contaminated: Soil
Cause of Contamination: Landfill
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-48
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

CITY OF SEATTLE SOLID WASTE DIV STS (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001127483

UST:

Facility ID: 97437
Install Date: 1/1/1962 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 97437
Install Date: 1/1/1962 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BW325
WNW
1/2-1
4451 ft.
Lower

SEATTLE S TRANSFER STA
8100 2ND AV S
SEATTLE, WA 98108
Site 3 of 3 in cluster BW

CSCSL S100484194
N/A

SHWS:

Facility ID: 2175
Responsible Unit: NW
Latitude: 47 31 53
Longitude: 122 19 53
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Release report received, awaiting assessment by Potentially Liable Person (PLP)
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Ground Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant medals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Suspected to be present

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SEATTLE S TRANSFER STA (Continued)

EDR ID Number
EPA ID Number

Database(s)

S100484194

Conventional Contaminants, Inorganic: Suspected to be present

Facility ID: 2175

Responsible Unit: NW

Latitude: 47 31 53

Longitude: 122 19 53

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Release report received, awaiting assessment by Potentially Liable Person (PLP)

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:

Not reported

Halogenated Organic Compounds:

Not reported

Horizontal Collection Method:

3

EPA Priority Pollutants - Metals and Cyanide:

Not reported

Metals - Other non-priority pollutant metals:

Not reported

Polychlorinated biPhenyls (PCBs):

Not reported

Pesticides:

Not reported

Petroleum Products:

Not reported

Phenolic Compounds:

Not reported

Non-Halogenated Solvents:

Not reported

Dioxin:

Not reported

Polynuclear Aromatic Hydrocarbons (PAH):

Not reported

Reactive Wastes:

Not reported

Corrosive Wastes:

Not reported

Radioactive Wastes:

Not reported

Asbestos:

Not reported

Conventional Contaminants, Organic:

Suspected to be present

Conventional Contaminants, Inorganic:

Suspected to be present

Facility ID: 2175

Responsible Unit: NW

Latitude: 47 31 53

Longitude: 122 19 53

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Release report received, awaiting assessment by Potentially Liable Person (PLP)

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:

Not reported

Halogenated Organic Compounds:

Not reported

Horizontal Collection Method:

3

EPA Priority Pollutants - Metals and Cyanide:

Not reported

Metals - Other non-priority pollutant metals:

Not reported

Polychlorinated biPhenyls (PCBs):

Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SEATTLE S TRANSFER STA (Continued)

EDR ID Number
EPA ID Number

Database(s)

S100484194

Pesticides:	Not reported
Petroleum Products:	Not reported
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Suspected to be present
Conventional Contaminants, Inorganic:	Suspected to be present

BX326 401 SOUTH WEBSTER
NW 401 SOUTH WEBSTER
1/2-1 SEATTLE, WA
4455 ft.
Lower Site 1 of 2 in cluster BX

ERNS 91230443
N/A

BX327 ATC DISTRIBUTION GROUP
NW 401 S WEBSTER
1/2-1 SEATTLE, WA 98108
4455 ft.
Lower Site 2 of 2 in cluster BX

RCRIS-SQG 1000123970
FINDS WAD988466710
UST
WA ICR
LUST

RCRIS:
Owner: RPM MERIT
(360) 555-1212
EPA ID: WAD988466710
Contact: RON FOWLER
(206) 764-4646
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

LUST:

Facility ID:	2703	Ecology Region:	North Western
Release ID:	5411	Release Date:	8/19/1994 00:00:00
Release Status:	Cleanup Started	Status Date:	6/1/1995 00:00:00
Alternate Name:	RPM MERIT		
Affected Media:	Soil		

Facility ID:	2703	Ecology Region:	North Western
Release ID:	5411	Release Date:	8/19/1994 00:00:00
Release Status:	Cleanup Started	Status Date:	6/1/1995 00:00:00
Alternate Name:	RPM MERIT		
Affected Media:	Ground Water		

WA ICR:

Date Ecology Received Report: 08/19/1994
Contaminants Found at Site: Petroleum products

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

ATC DISTRIBUTION GROUP (Continued)

1000123970

Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-34
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 2703
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 2703
Install Date: 12/31/1964 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

328
NE
1/2-1
4460 ft.
Higher

AIR NATIONAL
7277 PERIMETER RD S 215 MAIN T
SEATTLE, WA 98108

RCRIS-SQG 1000455946
FINDS WAD988475570
CSCSL

RCRIS:

Owner: AIR NATIONAL
(360) 555-1212
EPA ID: WAD988475570
Contact: MICKELA SCHER
(206) 763-6920

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 59377658
Responsible Unit: NW
Latitude: 47 32 36
Longitude: 122 18 54
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AIR NATIONAL (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000455946

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Ground Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant medals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 59377658

Responsible Unit: NW

Latitude: 47 32 36

Longitude: 122 18 54

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant medals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AIR NATIONAL (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000455946

Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

BV329
NW
1/2-1
4476 ft.
Lower

UNITED IRON WORKS INC
7421 5TH AVE S
SEATTLE, WA 98108

Site 2 of 4 in cluster BV

FINDS 1005099135
000009024294

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

BV330
NW
1/2-1
4476 ft.
Lower

UNITED IRON WORKS INC
7421 5TH AVE S
SEATTLE, WA 98108

Site 3 of 4 in cluster BV

RCRIS-SQG 1001600537
WAH000008482

RCRIS:
Owner: TONY DAMGO
(206) 767-3630
EPA ID: WAH000008482
Contact: DWIGHT JACOBS
(206) 767-3630

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

BV331
NW
1/2-1
4476 ft.
Lower

UNITED IRON WORKS INC
7421 5TH AVE SO
SEATTLE, WA 98108

Site 4 of 4 in cluster BV

UST U001122229
N/A

UST:
Facility ID: 1019
Install Date: 1/1/1961 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BY332
WSW
1/2-1
4479 ft.
Higher

SUPERIOR PRECISION ANALYTICAL
309 S CLOVERDALE ST STE B24
SEATTLE, WA 98108

Site 1 of 3 in cluster BY

RCRIS-SQG 1000974276
WA0000915454

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SUPERIOR PRECISION ANALYTICAL (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000974276

RCRIS:

Owner: SUPERIOR PRECISION ANALYTICAL
(360) 555-1212
EPA ID: WA0000915454
Contact: KELLY GREENHAW
(206) 763-2992

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

BY333
WSW
1/2-1
4480 ft.
Higher

MAGNETIC PENETRANT SVCS CO
309 S CLOVERDALE ST UNIT B20
SEATTLE, WA 98108

RCRIS-SQG 1000314223
FINDS WAD057211393
FTTS

Site 2 of 3 in cluster BY

RCRIS:

Owner: MAGNETIC PENETRANT SVCS CO INC
(360) 555-1212
EPA ID: WAD057211393
Contact: RICK REESE
(206) 762-5855

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	05/13/1990
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/17/1990
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-LAND BAN REQUIREMENTS
Date Violation Determined:	05/13/1990
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/17/1990
Penalty Type:	Not reported

There are 2 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
	GENERATOR-LAND BAN REQUIREMENTS

Date of
Compliance
09/01/199
09/01/199

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MAGNETIC PENETRANT SVCS CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000314223

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BY334
WSW
1/2-1
4493 ft.
Higher

DISCOUNT DRIVE AXLE OF SEATTLE
309 S CLOVERDALE ST STE A11
SEATTLE, WA 98108

RCRIS-SQG 1000982894
FINDS WA0000915306

Site 3 of 3 in cluster BY

RCRIS:

Owner: DISCOUNT DRIVE AXLE
(360) 555-1212

EPA ID: WA0000915306

Contact: DONNY WEBSTER
(206) 768-9413

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BZ335
NNE
1/2-1
4501 ft.
Higher

KING CO INTL AIRPORT
7211 PERIMETER RD
SEATTLE, WA 98108

FINDS 1004613722
I10#19881227

Site 1 of 2 in cluster BZ

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

CA336
WNW
1/2-1
4505 ft.
Lower

GO DAN INDUSTRIES SEATTLE
7951 2ND AVE S
SEATTLE, WA 98108

RCRIS-SQG 1004614096
FINDS WAD982655201

Site 1 of 3 in cluster CA

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GO DAN INDUSTRIES SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004614096

RCRIS:

Owner: GO DAN INDUSTRIES SEATTLE
EPA ID: WAD982655201
Contact: ROBERT BURK
(206) 764-7028

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Toxic Chemical Release Inventory System (TRIS)

BZ337
NNE
1/2-1
4505 ft.
Higher

GALVIN FLYING SVC
7205 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG 1000433230
FINDS WAD041333519

Site 2 of 2 in cluster BZ

RCRIS:

Owner: GALVIN FLYING SERVICE INC
(360) 555-1212
EPA ID: WAD041333519
Contact: JEFF MORSE
(206) 763-0350

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CA338
WNW
1/2-1
4528 ft.
Lower

7901 2ND AV. S
SEATTLE, WA

HMIRS 200115412
N/A

Site 2 of 3 in cluster CA

CA339
WNW
1/2-1
4528 ft.
Lower

FORMULA CORP.
7901 2ND AVE. S.
SEATTLE, WA 98108

RCRIS-SQG 1000898140
FINDS 98108FRMLC79
TRIS
FTTS

Site 3 of 3 in cluster CA

FTTS:

Case Number: Not reported
Docket Number: 1092-04-16-325
Complaint Issued: 07/06/92

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FORMULA CORP. (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000898140

Complaint Closed: 09/01/92
Abatement Amount: 09/01/92
Proposed Penalty: 5000
Final Assessment: 2550
Final Order Date: 0
Close Date: 09/01/92
Violation: EPCRA, Nonreporting/Failure to RPT to EPA

FTTS Insp:

Region: 10
Inspected Date: 04/16/96
Insp Number: 04/16/96
Violation occurred: No
Inspector: BAKER
Investigation Type: General Product Review
Facility Function: Producer
Investig Reason: Neutral Scheme, Region
Legislation Code: FIFRA

Region: 10
Inspected Date: 06/13/91
Insp Number: 06/13/91
Violation occurred: No
Inspector: WATSON
Investigation Type: General Product Review
Facility Function: Producer
Investig Reason: Neutral Scheme, Region
Legislation Code: FIFRA

Region: 10
Inspected Date: 02/25/92
Insp Number: 02/25/92
Violation occurred: Yes
Inspector: DAVIS
Investigation Type: EPCRA, Enforcement, Federal Conducted
Facility Function: Manufacturer
Investig Reason: Neutral Scheme, Region
Legislation Code: EPCRA

RCRIS:

Owner: FORMULA CORP
EPA ID: WAD009245671
Contact: CHARLES WERNER
(206) 762-7000

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMULA CORP. (Continued)

1000898140

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

National Compliance Database (NCDB)

Resource Conservation and Recovery Act Information system (RCRAINFO)

Section Seven Tracking System (SSTS)

Toxic Chemical Release Inventory System (TRIS)

340
NNE
1/2-1
4532 ft.
Higher

GALVIN FLYING SERVICE INC
7149 PERIMETER RD S
SEATTLE, WA 98108

FINDS 1004614506
110005367101

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

CB341
NNE
1/2-1
4605 ft.
Higher

AMERICAN AVIONICS
7031 PERIMETER ROAD S.
SEATTLE, WA 98108

WA ICR S104484592
N/A

Site 1 of 6 in cluster CB

WA ICR:

Date Ecology Received Report: / /
Contaminants Found at Site: Total petroleum hydrocarbons
Media Contaminated: Soil
Cause of Contamination: Unknown
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-02
County Code: 17
Contact: Not reported
Report Title: Not reported

CC342
NW
1/2-1
4605 ft.
Lower

TRIM SYSTEMS OPERATING CO
701 S ORCHARD ST
SEATTLE, WA 98108

FINDS 1000349625
RCRIS-LQG 98108TMPRS70
TRIS

Site 1 of 3 in cluster CC

RCRIS:

Owner: TRIM SYSTEMS LLC
(614) 253-7263
EPA ID: WAD004906376
Contact: JOHN POST
(206) 762-1410

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	11943.90	D018	113.90

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

TRIM SYSTEMS OPERATING CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000349625

D039	113.90	D040	113.90
F002	3790.00	F003	320.00

Violation Status: Violations exist

Regulation Violated:	-200(1)(b) &-630(5)(a)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-200(1)(b) &-630(7)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-200(1)(d)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-200(2)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-180(1)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-140(2)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-017(2) &(4)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998
Regulation Violated:	-200(1)(e) &-330
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/03/1998

There are 8 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	01/15/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/28/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/16/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/16/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/28/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/28/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	04/14/1999
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/28/1999

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Emissions Trends (NET)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

CC343
NW
1/2-1
4605 ft.
Lower

ROYAL LINE CABINET CO SEATTLE
700 S ORCHARD ST
SEATTLE, WA 98108

Site 2 of 3 in cluster CC

RCRIS-SQG 1000106020
FINDS WAD099039489

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ROYAL LINE CABINET CO SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000106020

RCRIS:

Owner: ROYAL LINE CABINET CO
(360) 555-1212
EPA ID: WAD099039489
Contact: ROGER CURFMANON
(206) 767-9125

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CC344
NW
1/2-1
4605 ft.
Lower

ORCHARD ST DRUMS
701 S ORCHARD
SEATTLE, WA 98108
Site 3 of 3 in cluster CC

RCRIS-SQG 1000455954
WAD988474557

RCRIS:

Owner: MANCHESTER LABORATORY
(360) 555-1212
EPA ID: WAD988474557
Contact: CRAIG BAKER
(360) 867-7016

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

345
NW
1/2-1
4609 ft.
Lower

CUNNINGHAM MFG CO INC
318 S WEBSTER ST
SEATTLE, WA 98108

RCRIS-SQG 1000316161
FINDS WAD009271578

RCRIS:

Owner: CUNNINGHAM MFG CO INC
(206) 767-3713
EPA ID: WAD009271578
Contact: KEN STAHL
(206) 767-3713

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

CUNNINGHAM MFG CO INC (Continued)

1000316161

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

346
NNW
1/2-1
4610 ft.
Lower

TYEE INDUSTRIES
765 S MYRTLE ST
SEATTLE, WA 98108

RCRIS-SQG 1001490206
FINDS WAD009244179

RCRIS:

Owner: TYEE INDUSTRIES
EPA ID: WAD009244179
Contact: Haz-Waste Mgr
(206) 763-0990
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
National Compliance Database (NCDB)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CB347
NNE
1/2-1
4613 ft.
Higher

AMERICAN AVIONICS KING CNTY AIRPORT
7023 PERIMETER RD S
SEATTLE, WA 98108

CSCSL S104490864
N/A

Site 2 of 6 in cluster CB

SHWS:

Facility ID: 39659753
Responsible Unit: NW
Latitude: 47 32 22
Longitude: 122 18 21
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant medals: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AMERICAN AVIONICS KING CNTY AIRPORT (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104490864

Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Confirmed above MTCA cleanup levels
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 39659753

Responsible Unit: NW

Latitude: 47 32 22

Longitude: 122 18 21

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Ground Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Not reported

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Suspected to be present

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

CB348 GALVIN FLYING CENTER
NNE 7001 PERIMETER RD
1/2-1 SEATTLE, WA 98108
4638 ft.
Higher Site 3 of 6 in cluster CB

LUST S104546814
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GALVIN FLYING CENTER (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104546814

LUST:

Facility ID: 507162 Ecology Region: North Western
Release ID: 527809 Release Date: 2/24/1999 00:00:00
Release Status: Cleanup Started Status Date: 2/5/1999 00:00:00
Alternate Name: GALVINS FLYING SERVICE
Affected Media: Soil

Facility ID: 507162 Ecology Region: North Western
Release ID: 527809 Release Date: 2/24/1999 00:00:00
Release Status: Reported Cleaned Up Status Date: 2/24/1999 00:00:00
Alternate Name: GALVINS FLYING SERVICE
Affected Media: Soil

CB349 GALVIN S FLYING SERVICE
NNE 7001 PERIMETER ROAD
1/2-1 SEATTLE, WA 98108

WA ICR S104485879
N/A

4638 ft.
Higher

Site 4 of 6 in cluster CB

WA ICR:

Date Ecology Received Report: 02/24/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-23
County Code: 17
Contact: Not reported
Report Title: Not reported

CB350 GALVIN FLYING CENTER
NNE 7001 PERIMETER RD
1/2-1 SEATTLE, WA 98108

UST U003665848
N/A

4638 ft.
Higher

Site 5 of 6 in cluster CB

UST:

Facility ID: 507162
Install Date: Not reported
Capacity: Not reported
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CB351 7001 PERIMETER RD S
NNE SEATTLE, WA

SPILLS S105392010
N/A

4638 ft.
Higher

Site 6 of 6 in cluster CB

WA SPILL:

Facility ID: 511265
Date Received: 02/24/2000
Business Name: FLYING

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

(Continued)

EDR ID Number
EPA ID Number

Database(s)

Material Desc : PETROLEUM - WASTE/USED OIL
Medium: SOIL
Material Qty: Not reported
Material Units: Not reported

S105392010

CD352 ADVANCE ELECTROPLATING INC
SSW 9585 8TH AVE S
1/2-1 SEATTLE, WA 98108
4647 ft.
Higher Site 1 of 2 in cluster CD

RCRIS-SQG 1000151495
FINDS WAD009278847
CERC-NFRAP
UST
CSCSL
CA HAZNET

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Non NPL Code: Referred to Removal - NFRAP
Ownership Status: Other

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
Assessment: PRELIMINARY ASSESSMENT
Assessment: SITE INSPECTION
Assessment: Lodged By DOJ
Assessment: REMOVAL
Assessment: CONSENT DECREE

Completed: 01/01/1983
Completed: 05/07/1985
Completed: 06/30/1986
Completed: 02/01/1996
Completed: 04/05/1996
Completed: 04/29/1996

RCRIS:

Owner: ADVANCED CO
(360) 555-1212
EPA ID: WAD009278847
Contact: LEIGH LANEY
(206) 762-2390

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: 200(1)(D)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1992

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 11/10/1992
Penalty Type: Not reported

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 04/26/1993
Penalty Type: Not reported

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/23/1993
Penalty Type: Not reported

Regulation Violated: 200(1)(C)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1992

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 11/10/1992
Penalty Type: Not reported

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 04/26/1993

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ADVANCE ELECTROPLATING INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000151495

Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/23/1993
Penalty Type:	Not reported
Regulation Violated:	630(5)(A)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	11/10/1992
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/10/1992
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/26/1993
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/23/1993
Penalty Type:	Not reported
Regulation Violated:	145
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	11/10/1992
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/10/1992
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/26/1993
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/23/1993
Penalty Type:	Not reported
Regulation Violated:	210
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	11/10/1992
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/10/1992
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/26/1993
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/23/1993
Penalty Type:	Not reported
Regulation Violated:	330
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	11/10/1992
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/10/1992
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/26/1993
Penalty Type:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ADVANCE ELECTROPLATING INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000151495

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/23/1993
Penalty Type: Not reported
Regulation Violated: 350
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1992
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 11/10/1992
Penalty Type: Not reported
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 04/26/1993
Penalty Type: Not reported
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/23/1993
Penalty Type: Not reported

There are 7 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199
	GENERATOR-GENERAL REQUIREMENTS	12/10/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Enforcement Docket System (DOCKET)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

SHWS:

Facility ID: 2079
Responsible Unit: NW
Latitude: 47 31 2
Longitude: 122 19 24
Ecology Site Status relative to the MTCA cleanup process:
Ranked, Awaiting Remedial Action (RA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment
Affected Media: Air
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant medals: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ADVANCE ELECTROPLATING INC (Continued)

1000151495

Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Not reported
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

Facility ID: 2079

Responsible Unit: NW

Latitude: 47 31 2

Longitude: 122 19 24

Ecology Site Status relative to the MTCA cleanup process:

Ranked, Awaiting Remedial Action (RA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

5 - Lowest assessed risk to human health and to the environment

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:	Not reported
-----------------------------	--------------

Halogenated Organic Compounds:	Not reported
--------------------------------	--------------

Horizontal Collection Method:	3
-------------------------------	---

EPA Priority Pollutants - Metals and Cyanide:	Confirmed above MTCA cleanup levels
---	-------------------------------------

Metals - Other non-priority pollutant metals:	Not reported
---	--------------

Polychlorinated biPhenyls (PCBs):	Not reported
-----------------------------------	--------------

Pesticides:	Not reported
-------------	--------------

Petroleum Products:	Not reported
---------------------	--------------

Phenolic Compounds:	Not reported
---------------------	--------------

Non-Halogenated Solvents:	Not reported
---------------------------	--------------

Dioxin:	Not reported
---------	--------------

Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
--	--------------

Reactive Wastes:	Not reported
------------------	--------------

Corrosive Wastes:	Suspected to be present
-------------------	-------------------------

Radioactive Wastes:	Not reported
---------------------	--------------

Asbestos:	Not reported
-----------	--------------

Conventional Contaminants, Organic:	Not reported
-------------------------------------	--------------

Conventional Contaminants, Inorganic:	Confirmed above MTCA cleanup levels
---------------------------------------	-------------------------------------

Facility ID: 2079

Responsible Unit: NW

Latitude: 47 31 2

Longitude: 122 19 24

Ecology Site Status relative to the MTCA cleanup process:

Ranked, Awaiting Remedial Action (RA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

5 - Lowest assessed risk to human health and to the environment

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

ADVANCE ELECTROPLATING INC (Continued)

1000151495

Affected Media: Sediments
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant medals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Suspected to be present

Facility ID: 2079
Responsible Unit: NW
Latitude: 47 31 2
Longitude: 122 19 24

Ecology Site Status relative to the MTCA cleanup process:
Ranked, Awaiting Remedial Action (RA)

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment

Affected Media: Ground Water
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant medals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Suspected to be present

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ADVANCE ELECTROPLATING INC (Continued)

1000151495

Facility ID: 2079
Responsible Unit: NW
Latitude: 47 31 2
Longitude: 122 19 24
Ecology Site Status relative to the MTCA cleanup process:
Ranked, Awaiting Remedial Action (RA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has
been confirmed by laboratory analysis (or field determination in the case of petroleum
contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Suspected to be present

UST:

Facility ID: 2221
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

HAZNET:

Gepaid: WAD009278847
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: .6000
Category: Liquids with cyanides > 1000 mg/l
Disposal Method: Transfer Station
Contact: T BOYD COLEMAN
Telephone: (206) 762-2390
Mailing Address: 9585 8TH AVE S
SEATTLE, WA 98108 - 4911
County: 99

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

ADVANCE ELECTROPLATING INC (Continued)

1000151495

Gepaid: WAD009278847
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: .1500
Category: Other organic solids
Disposal Method: Transfer Station
Contact: T BOYD COLEMAN
Telephone: (206) 762-2390
Mailing Address: 9585 8TH AVE S
SEATTLE, WA 98108 - 4911
County 99

Gepaid: WAD009278847
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: .2750
Category:
Disposal Method: Recycler
Contact: T BOYD COLEMAN
Telephone: (206) 762-2390
Mailing Address: 9585 8TH AVE S
SEATTLE, WA 98108 - 4911
County 99

Gepaid: WAD009278847
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: 33.7120
Category: Liquids with pH <UN-> 2
Disposal Method: Transfer Station
Contact: T BOYD COLEMAN
Telephone: (206) 762-2390
Mailing Address: 9585 8TH AVE S
SEATTLE, WA 98108 - 4911
County 99

Gepaid: WAD009278847
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: .1420
Category:
Disposal Method: Transfer Station
Contact: T BOYD COLEMAN
Telephone: (206) 762-2390
Mailing Address: 9585 8TH AVE S
SEATTLE, WA 98108 - 4911
County 99

The CA HAZNET database contains 10 additional records for this site.
Please contact your EDR Account Executive for more information.

353
NW
1/2-1
4652 ft.
Lower

SEATTLE SLUDGE INTERIM PROJECT
7417 4TH AVE S
SEATTLE, WA 98018

RCRIS-SQG 1000706892
FINDS WAD988503066

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SEATTLE SLUDGE INTERIM PROJECT (Continued)

1000706892

RCRIS:

Owner: SEATTLE SLUDGE INTERIM PROJECT
(360) 555-1212
EPA ID: WAD988503066
Contact: BART LYNAM
(206) 285-0140

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

354
NNE
1/2-1
4656 ft.
Higher

GALVIN FLYING SERVICE
6987 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG 1000878739
FINDS WAD988520615

RCRIS:

Owner: PETER ANDERSON
(206) 763-0350
EPA ID: WAD988520615
Contact: JAY CHENEY
(206) 763-0350

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: 200(1)(c)(d)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 02/13/1997

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 02/13/1997
Penalty Type: Not reported

Regulation Violated: 630(5)(a)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 02/13/1997

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 02/13/1997
Penalty Type: Not reported

Regulation Violated: 180
Area of Violation: GENERATOR-MANIFEST REQUIREMENTS
Date Violation Determined: 02/13/1997

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 02/13/1997
Penalty Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GALVIN FLYING SERVICE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000878739

There are 3 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	02/14/199
	GENERATOR-GENERAL REQUIREMENTS	02/14/199
	GENERATOR-MANIFEST REQUIREMENTS	03/11/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CD355
SSW
1/2-1
4691 ft.
Higher

CONTAINER CARE PUGET SOUND
9600 8TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000395894
FINDS WAD988469144

Site 2 of 2 in cluster CD

RCRIS:

Owner: CONTAINER CARE PUGET SOUND
(360) 555-1212
EPA ID: WAD988469144
Contact: JODY HORGAN
(206) 767-9960

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CE356
WNW
1/2-1
4693 ft.
Lower

GUINNS AUTOMOTIVE & ELECTRIC
245 S AUSTIN
SEATTLE, WA 98108

FINDS 1004990924
000007560074

Site 1 of 3 in cluster CE

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CE357
WNW
1/2-1
4693 ft.
Lower

GUINNS AUTOMOTIVE & ELECTRIC
245 S AUSTIN
SEATTLE, WA 98108

RCRIS-SQG 1001234072
WAH000004846

Site 2 of 3 in cluster CE

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GUINNS AUTOMOTIVE & ELECTRIC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001234072

RCRIS:

Owner: JIM & CAROL GUINN

(206) 722-6113

EPA ID: WAH000004846

Contact: JIM & CAROL GUINN

(206) 722-6113

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

358
SW
1/2-1
4713 ft.
Higher

NORTHWEST GRATING PRODUCTS INC
9230 4TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1001969538
FINDS WAD988492310

RCRIS:

Owner: NORTHWEST GRATING PRODUCTS INC

EPA ID: WAD988492310

Contact: RANDALL BREIWICK

(206) 767-3000

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CF359
West
1/2-1
4719 ft.
Lower

OCEAN TERMINALS INC
8151 OCCIDENTAL AVE SOUTH
SEATTLE, WA 98108

UST U000920554
N/A

Site 1 of 2 in cluster CF

UST:

Facility ID: 3729

Install Date: 12/31/1964 0:00

Capacity: 111 to 1,100 Gallons

Status: Not reported

Tank Name: UNLEADED GASOLINE

Substance: NW

Compartment #: Not reported

Ecology Region: 1

CF360
West
1/2-1
4719 ft.
Lower

NORTH STAR ICE EQUIPMENT INC
8151 OCCIDENTAL AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000659556
FINDS WAD988492302

Site 2 of 2 in cluster CF

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTH STAR ICE EQUIPMENT INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000659556

RCRIS:

Owner: NORTH STAR ICE EQUIPMENT INC
(206) 763-7300
EPA ID: WAD988492302
Contact: DAVID RODGERS
(206) 763-7300

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CG361
WNW
1/2-1
4723 ft.
Lower

**ROYAL HYWAY TOURS
255 SOUTH HOLDEN ST.
SEATTLE, WA 98108**

UST U003028180
WA ICR N/A
LUST

Site 1 of 3 in cluster CG

LUST:

Facility ID: 7524 Ecology Region: North Western
Release ID: 5552 Release Date: 10/11/1994 00:00:00
Release Status: Cleanup Started Status Date: 10/11/1994 00:00:00
Alternate Name: ROYAL HWY TOURS COACH MAINTENANCE
Affected Media: Soil

Facility ID: 7524 Ecology Region: North Western
Release ID: 5552 Release Date: 10/11/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: ROYAL HWY TOURS COACH MAINTENANCE
Affected Media: Soil

WA ICR:

Date Ecology Received Report: 10/25/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 93-39
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 7524
Install Date: 2/15/1971 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

ROYAL HYWAY TOURS (Continued)

U003028180

Facility ID: 7524
Install Date: 2/15/1971 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CH362
WNW
1/2-1
4731 ft.
Lower

TACOMA SEATTLE TRAILER REPAIR
150 S KENYON ST
SEATTLE, WA 98108

UST U000590773
LUST N/A

Site 1 of 2 in cluster CH

LUST:

Facility ID: 6109 Ecology Region: North Western
Release ID: 519164 Release Date: 12/16/1999 00:00:00
Release Status: Cleanup Started Status Date: 8/26/1997 00:00:00
Alternate Name: TACOMA & SEATTLE TRAILER REPAIR
Affected Media: Soil

Facility ID: 6109 Ecology Region: North Western
Release ID: 519164 Release Date: 12/16/1999 00:00:00
Release Status: Reported Cleaned Up Status Date: 12/16/1999 00:00:00
Alternate Name: TACOMA & SEATTLE TRAILER REPAIR
Affected Media: Soil

UST:

Facility ID: 6109
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 6109
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: MOTOR OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CH363
WNW
1/2-1
4731 ft.
Lower

TACOMA SEATTLE TRAILER
150 S. KENYON ST.
SEATTLE, WA 98108

WA ICR S104485821
N/A

Site 2 of 2 in cluster CH

WA ICR:

Date Ecology Received Report: 12/16/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

TACOMA SEATTLE TRAILER (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104485821

Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-21
County Code: 17
Contact: Not reported
Report Title: Not reported

364
NNW
1/2-1
4749 ft.
Lower

RICHARD DONDERO
7047 E MARGINAL WAY S
SEATTLE, WA 98121

UST U003604864
N/A

UST:

Facility ID: 498231
Install Date: Not reported
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 498231
Install Date: Not reported
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CG365
WNW
1/2-1
4752 ft.
Lower

FIRE KING OF SEATTLE
240 S. HOLDEN ST.
SEATTLE, WA 98108

WA ICR S104486780
N/A

Site 2 of 3 in cluster CG

WA ICR:

Date Ecology Received Report: 08/18/1995
Contaminants Found at Site: PCB's
Petroleum products
Media Contaminated: Soil
Cause of Contamination: Spill
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-08
County Code: 17
Contact: Not reported
Report Title: Not reported

CI366
NNW
1/2-1
4758 ft.
Lower

NELSON TRUCKING CO. LEASEWAY CORPORATI
719 SO. MYRTLE ST
SEATTLE, WA 98108

UST U003027286
N/A

Site 1 of 2 in cluster CI

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

NELSON TRUCKING CO. LEASEWAY CORPORATI (Continued)

U003027286

UST:

Facility ID: 522
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 522
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 522
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

367
NNW
1/2-1
4765 ft.
Lower

WA DNR CORSON AVE SITE HAT BOO
6800 E MARGINAL WAY & CORSON A
SEATTLE, WA 98108

RCRIS-SQG 1000352112
FINDS WAD980723175

RCRIS:

Owner: WA DNR
(360) 555-1212
EPA ID: WAD980723175
Contact: AYMAN OUBARI
(360) 753-2093
Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CG368
WNW
1/2-1
4770 ft.
Lower

BESCO ROOFING INC
233 S HOLDEN STREET
SEATTLE, WA 98108
Site 3 of 3 in cluster CG

UST U000925284
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BESCO ROOFING INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

U000925284

UST:

Facility ID: 100876
Install Date: 1/1/1984 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 100876
Install Date: 1/1/1984 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CE369
WNW
1/2-1
4771 ft.
Lower

211 S AUSTIN, WEST SEATTLE
SEATTLE, WA

SPILLS S105391625
N/A

Site 3 of 3 in cluster CE

WA SPILL:

Facility ID: 508772
Date Received: 01/18/2000
Business Name: BATTERY SUPPLY
Material Desc: OTHER HAZARDOUS
Medium: SURFACE WATER-FRESH
Material Qty: Not reported
Material Units: Not reported

CI370
NNW
1/2-1
4787 ft.
Lower

COMMERCIAL WELDING & FABRICATION INC
711 S MYRTLE ST
SEATTLE, WA 98108

RCRIS-SQG 1000658799
FINDS WAD988484556

Site 2 of 2 in cluster CI

RCRIS:

Owner: COMMERCIAL WELDING & FABRICATION INC
EPA ID: WAD988484556
Contact: DONALD THOMPSON
(206) 767-4211

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

COMMERCIAL WELDING & FABRICATION INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

Violation Status: No violations found

1000658799

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CJ371
West
1/2-1
4794 ft.
Lower

INTERNATIONAL CONSTRUCTION EQUIPMENT
8101 OCCIDENTAL AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000217067
FINDS WAD982821076

Site 1 of 2 in cluster CJ

RCRIS:

Owner: THOMAS CUNNINGHAM
(800) 438-9281
EPA ID: WAD982821076
Contact: MICHAEL CLARK
(206) 764-4787

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CJ372
West
1/2-1
4794 ft.
Lower

TRANSFER STA BARREL
8100 OCCIDENTAL AVE S 033
SEATTLE, WA 98108

RCRIS-SQG 1000879079
FINDS WAD988524237

Site 2 of 2 in cluster CJ

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD988524237
Contact: KAREN RENNAKER
(425) 649-7063

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

TRANSFER STA BARREL (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000879079

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

373
NNE
1/2-1
4821 ft.
Higher

TEXACO INC
7000 AIRPORT ROAD SOUTH
SEATTLE, WA 98108

UST U000588443
N/A

UST:

Facility ID: 3435
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 3435
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 3435
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 3435
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 3435
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Database(s)

CK374 RSTS KENYON ST
WNW 130 S KENYON ST
1/2-1 SEATTLE, WA 98108
4865 ft.
Lower

RCRIS-SQG 1000334255
FINDS WAD075124800

Site 1 of 2 in cluster CK

RCRIS:

Owner: RYDER STUDENT TRANSP
(206) 763-1484

EPA ID: WAD075124800

Contact: RAY SHARRAH
(206) 763-1484

Classification: N, Conditionally Exempt Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CK375 RYDER STUDENT TRANSPORTATION SERVICES, INC.
WNW 130 S KENYON ST
1/2-1 SEATTLE, WA 98108
4865 ft.
Lower

UST U003311083
CSCSL N/A
WA ICR
LUST

Site 2 of 2 in cluster CK

SHWS:

Facility ID: 63293426

Responsible Unit: NW

Latitude: 47 31 55

Longitude: 122 20 3

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Final Independent Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Not reported

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

RYDER STUDENT TRANSPORTATION SERVICES, INC. (Continued)

U003311083

Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

LUST:

Facility ID: 425723 Ecology Region: North Western
Release ID: 425728 Release Date: 8/13/1997 00:00:00
Release Status: Reported Cleaned Up Status Date: 8/13/1997 00:00:00
Alternate Name: RYDER
Affected Media: Soil

WA ICR:

Date Ecology Received Report: 10/20/1997
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 95-13
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/29/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-15
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 425723
Install Date: Not reported
Capacity: Not reported
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 425723
Install Date: Not reported
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

RYDER STUDENT TRANSPORTATION SERVICES, INC. (Continued)

U003311083

Facility ID: 425723
Install Date: 8/29/1997 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 425723
Install Date: Not reported
Capacity: Not reported
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CL376
NW
1/2-1
4895 ft.
Lower

MYRTLE STREET PROPERTY
606 S MYRTLE ST
SEATTLE, WA 98108

CSCSL S104971231
N/A

Site 1 of 7 in cluster CL

SHWS:

Facility ID: 12153465
Responsible Unit: NW
Latitude: 47 32 21
Longitude: 122 19 32
Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 2

EPA Priority Pollutants - Metals and Cyanide: Not reported

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

MYRTLE STREET PROPERTY (Continued)

S104971231

Facility ID: 12153465
Responsible Unit: NW
Latitude: 47 32 21
Longitude: 122 19 32
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 2
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

377
NW
1/2-1
4898 ft.
Lower

BOYER ALASKA BARGE LINES INC
7318 4TH AVE S
SEATTLE, WA 98108

PADS 1000209864
RCRIS-SQG WAD045684990
FINDS

RCRIS:

Owner: BOYER ALASKA BARGE LINES INC
EPA ID: WAD045684990
Contact: J AMO
(206) 763-8575

Classification: Handler transports wastes for hire, Conditionally Exempt Small Quantity Generator

Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOYER ALASKA BARGE LINES INC (Continued)

1000209864

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Enforcement Docket System (DOCKET)
Facility Registry System (FRS)
PCB Handler Activity Data System (PADS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CL378 SEATTLE IRON METALS CORP MYRTLE ST
NW 601 S MYRTLE ST
1/2-1 SEATTLE, WA 98108
4900 ft.
Lower Site 2 of 7 in cluster CL

FINDS 1005127399
000009370294

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CL379 601 SOUTH MYRTLE STREET
NW 601 SOUTH MYRTLE STREET
1/2-1 SEATTLE, WA 0
4900 ft.
Lower Site 3 of 7 in cluster CL

ERNS 2000527339
N/A

CL380 SEATTLE IRON METALS CORP MYRTLE ST
NW 601 S MYRTLE ST
1/2-1 SEATTLE, WA 98108
4900 ft.
Lower Site 4 of 7 in cluster CL

RCRIS-SQG 1001969703
WAH000010678

RCRIS:

Owner: SIMCO PROPERTIES
(206) 682-0040
EPA ID: WAH000010678
Contact: ALAN SIDELL
(206) 682-0040

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

CL381 601 S. MYRTLE ST
NW SEATTLE, WA
1/2-1
4900 ft.
Lower Site 5 of 7 in cluster CL

SPILLS S105392515
N/A

WA SPILL:

Facility ID: 510299
Date Received: 04/10/2000
Business Name: MANUFACTURER
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: SURFACE WATER-FRESH

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S105392515

Material Qty: 80
Material Units: GALLON

CL382
NW
1/2-1
4900 ft.
Lower

MANSON CONSTRUCTION CO
601 S MYRTLE ST
SEATTLE, WA 98108

UST U000594924
N/A

Site 6 of 7 in cluster CL

UST:

Facility ID: 10855
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10855
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CL383
NW
1/2-1
4900 ft.
Lower

601 S MYRTLE ST
SEATTLE, WA

SPILLS S105392712
N/A

Site 7 of 7 in cluster CL

WA SPILL:

Facility ID: 510912
Date Received: 04/27/2000
Business Name: MANUFACTURER
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: SOIL
Material Qty: 100
Material Units: GALLON

384
NW
1/2-1
4913 ft.
Lower

PROFESSIONAL SERVICE INDUSTRIE
7400 3RD AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000420831
FINDS WAD027463165
UST

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PROFESSIONAL SERVICE INDUSTRIE (Continued)

1000420831

RCRIS:

Owner: PROFESSIONAL SVC INDUSTRIE
(360) 555-1212
EPA ID: WAD027463165
Contact: BRUCE MACILROY
(206) 762-4664

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

UST:

Facility ID: 53
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CM385 LIQUID AIR CORP.
WNW 7500 2ND AVE. SOUTH
1/2-1 SEATTLE, WA 98108
4914 ft.
Lower Site 1 of 4 in cluster CM

UST U003028014
N/A

UST:

Facility ID: 7069
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7069
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CM386 SAFWAY STEEL PRODUCTS
WNW 7501 2ND AVE SOUTH
1/2-1 SEATTLE, WA 98108
4914 ft.
Lower Site 2 of 4 in cluster CM

UST U003025652
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFWAY STEEL PRODUCTS (Continued)

U003025652

UST:

Facility ID: 11683
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CM387
WNW
1/2-1
4914 ft.
Lower

LIQUID AIR CORP OF N AMERICA
7500 2ND AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000425126
FINDS WAD980725014
TSCA

Site 3 of 4 in cluster CM

RCRIS:

Owner: LIQUID AIR CORP
(360) 555-1212
EPA ID: WAD980725014
Contact: BILL THOMAS
(253) 383-3637

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

388
SW
1/2-1
4968 ft.
Higher

SCREEN MATIC ARTS
9354 4TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000202108
FINDS WAD067166355

RCRIS:

Owner: SCREEN MATIC ARTS
EPA ID: WAD067166355
Contact: Haz-Waste Mgr
(206) 632-0550

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SCREEN MATIC ARTS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000202108

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CM389
WNW
1/2-1
4972 ft.
Lower

PACIFIC AMERICAN COMMERCIAL CO
7400 2ND AVE S
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1001805976
WAD009279050

Site 4 of 4 in cluster CM

RCRIS:

Owner: PACIFIC AMERICAN COMMERCIAL CO
(206) 762-3550

EPA ID: WAD009279050

Contact: TOM GIBBONS
(206) 762-3550

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

390
WNW
1/2-1
4995 ft.
Lower

WE PAINTERS INC
110 S KENYON
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1001092212
WAR000008755

RCRIS:

Owner: GEORGE CROSBY
(206) 767-3330

EPA ID: WAR000008755

Contact: GEORGE CROSBY
(206) 767-3330

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WE PAINTERS INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001092212

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CN391
SW
1/2-1
4997 ft.
Higher

TOXGON CORP SEATTLE
631 S 96TH ST
SEATTLE, WA 98108

CSCSL S103083958
N/A

Site 1 of 6 in cluster CN

SHWS:

Facility ID: 2329
Responsible Unit: NW
Latitude: 47 31 1
Longitude: 122 19 34

Ecology Site Status relative to the MTCA cleanup process:

Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Ground Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:

Not reported

Halogenated Organic Compounds:

Suspected to be present

Horizontal Collection Method:

3

EPA Priority Pollutants - Metals and Cyanide:

Suspected to be present

Metals - Other non-priority pollutant metals:

Not reported

Polychlorinated biPhenyls (PCBs):

Not reported

Pesticides:

Not reported

Petroleum Products:

Not reported

Phenolic Compounds:

Suspected to be present

Non-Halogenated Solvents:

Suspected to be present

Dioxin:

Not reported

Polynuclear Aromatic Hydrocarbons (PAH):

Suspected to be present

Reactive Wastes:

Not reported

Corrosive Wastes:

Not reported

Radioactive Wastes:

Not reported

Asbestos:

Not reported

Conventional Contaminants, Organic:

Not reported

Conventional Contaminants, Inorganic:

Suspected to be present

Facility ID: 2329

Responsible Unit: NW

Latitude: 47 31 1

Longitude: 122 19 34

Ecology Site Status relative to the MTCA cleanup process:

Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

TOXGON CORP SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

S103083958

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Suspected to be present
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant medals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Not reported
Phenolic Compounds:	Suspected to be present
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Suspected to be present
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Suspected to be present

Facility ID: 2329
Responsible Unit: NW
Latitude: 47 31 1
Longitude: 122 19 34

Ecology Site Status relative to the MTCA cleanup process:

Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Suspected to be present
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant medals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Not reported
Phenolic Compounds:	Suspected to be present
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Suspected to be present
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Suspected to be present

Facility ID: 2329
Responsible Unit: NW
Latitude: 47 31 1
Longitude: 122 19 34

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TOXGON CORP SEATTLE (Continued)

S103083958

Ecology Site Status relative to the MTCA cleanup process:

Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Sediments

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Suspected to be present

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Not reported

Phenolic Compounds: Suspected to be present

Non-Halogenated Solvents: Suspected to be present

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Suspected to be present

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Suspected to be present

CN392
SW
1/2-1
4997 ft.
Higher

PENBERTHY ELECTROMELT INTL INC
631 S 96TH ST
SEATTLE, WA 98108

Site 2 of 6 in cluster CN

RCRIS-SQG 1000163210
FINDS WAD061669644
RCRIS-TSD
CORRACTS

CORRACTS Data:

EPA Id: WAD061669644
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 12/13/1995
Corrective Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary

EPA Id: WAD061669644
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 05/21/1997
Corrective Action: CA075HI - CA Prioritization, Facility or areawas assigned a high corrective action priority

EPA Id: WAD061669644
Region: 10

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PENBERTHY ELECTROMELT INTL INC (Continued)

1000163210

State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 05/21/1997
Corrective Action: CA100DC - RFI Imposition , Focused data collection required for stabilization evaluation

EPA Id: WAD061669644
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 12/13/1995
Corrective Action: CA225NR - Stabilization Measures Evaluation, This facility is , not amenable to stabilization activity at the, present time for reasons other than (1) it appears to be technically, infeasible or inappropriate (NF) or (2) there is a lack of technical, information (IN). Reasons for this conclusion may be the status of, closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other, administrative considerations

EPA Id: WAD061669644
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 02/03/1998
Corrective Action: CA725IN - Current Human Exposures Under Control , More information is needed to make a determination

The CORRACTS database contains 4 additional records for this site.
Please contact your EDR Account Executive for more information.

RCRIS Corrective Action Summary:

Event: Current Human Exposures under Control, More information is needed to make a determination.
Event Date: 07/25/2001
Event: Igration of Contaminated Groundwater under Control, More information is needed to make a determination.
Event Date: 07/25/2001
Event: RFI Workplan Approved
Event Date: 01/08/2001
Event: Current Human Exposures under Control, More information is needed to make a determination.
Event Date: 06/29/2000
Event: Igration of Contaminated Groundwater under Control, More information is needed to make a determination.
Event Date: 06/29/2000

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

PENBERTHY ELECTROMELT INTL INC (Continued)

1000163210

Event: Current Human Exposures under Control, More information is needed to make a determination.
Event Date: 02/03/1998
Event: Igration of Contaminated Groundwater under Control, More information is needed to make a determination.
Event Date: 02/03/1998
Event: CA Prioritization, Facility or area was assigned a high corrective action priority.
Event Date: 05/21/1997
Event: RFI Imposition, Focused data collection required for stabilization evaluation.
Event Date: 05/21/1997
Event: RFA Determination Of Need For An RFI, RFI is Necessary;
Event Date: 12/13/1995
Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
Event Date: 12/13/1995

RCRIS:

Owner: TOXGON CORP SEATTLE
EPA ID: WAD061669644
Contact: WILLIAM WHITACRE
(206) 762-5583

Rank Status: 1
Rank Date: 10/01/1991
Classification: N, TSDF
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: -200(1)(a)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 01/22/2001
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 02/01/2001
Penalty Type: Not reported

Regulation Violated: -200(1)(c)(d)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 01/22/2001
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 02/01/2001
Penalty Type: Not reported

Regulation Violated: -200(1)(A)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 01/26/2000
Enforcement Action: WRITTEN INFORMAL

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PENBERTHY ELECTROMELT INTL INC (Continued)

1000163210

Enforcement Action Date:	03/01/2000
Penalty Type:	Not reported
Regulation Violated:	-016(5)(D)(II)-170/-070(3)
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	01/26/2000
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	03/01/2000
Penalty Type:	Not reported
Regulation Violated:	-400/40cfr265.110,111,112(a&b)
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	01/26/2000
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	03/01/2000
Penalty Type:	Not reported
Regulation Violated:	-400/40CFR265.110,111,112(A&B)
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	01/26/2000
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	03/01/2000
Penalty Type:	Not reported
Regulation Violated:	-303-210(1)
Area of Violation:	TSD-MANIFEST REQUIREMENTS
Date Violation Determined:	11/22/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/22/1991
Penalty Type:	Not reported
Regulation Violated:	-320(d)
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	11/22/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/22/1991
Penalty Type:	Not reported
Regulation Violated:	40 CFR 265.142(a)(1)
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	11/22/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/22/1991
Penalty Type:	Not reported
Regulation Violated:	40 CFR 265.112(b)
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	11/22/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/22/1991
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-CORRECTIVE ACTION COMPLIANCE SCHEDULE
Date Violation Determined:	02/28/1990
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	02/28/1990

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PENBERTHY ELECTROMELT INTL INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000163210

Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	11/16/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
Date Violation Determined:	11/16/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	11/16/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	08/08/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
Date Violation Determined:	08/08/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	08/08/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	08/08/1989
Regulation Violated:	Not reported
Area of Violation:	TSD-LAND BAN REQUIREMENTS
Date Violation Determined:	08/08/1989

There are 19 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	02/03/200
	GENERATOR-GENERAL REQUIREMENTS	03/18/200
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	
	TSD-GENERAL STANDARDS	
	TSD-GENERAL STANDARDS	
Compliance Evaluation Inspection	TSD-MANIFEST REQUIREMENTS	06/04/199
	TSD-GENERAL STANDARDS	06/08/199
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	11/22/199
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	11/22/199
Compliance Schedule Evaluation	TSD-CORRECTIVE ACTION COMPLIANCE SCHEDULE	02/28/199
Compliance Evaluation Inspection	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	03/10/199
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	03/10/199
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	03/10/199
Compliance Evaluation Inspection	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	07/04/199
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	07/04/199
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	07/04/199
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	07/04/199
	TSD-LAND BAN REQUIREMENTS	07/04/199

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PENBERTHY ELECTROMELT INTL INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000163210

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CN393
SW
1/2-1
5004 ft.
Higher

ALLIED BODY WORKS INC
625 S 96TH ST
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000659940
WAD988496196

Site 3 of 6 in cluster CN

RCRIS:

Owner: RICHARD MINICE
(206) 763-7811
EPA ID: WAD988496196
Contact: PAT ROBINSON
(206) 763-7811
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDf Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CO394
WNW
1/2-1
5009 ft.
Lower

WG CLARK CONSTRUCTION OCCIDENTAL AVE
7958 OCCIDENTAL AVE S
SEATTLE, WA 98108

RCRIS-SQG

1001969733
WAH000010975

Site 1 of 3 in cluster CO

RCRIS:

Owner: WG CLARK CONSTRUCTION OCCIDENTAL AVE
(206) 624-9244
EPA ID: WAH000010975
Contact: JEFF FRANKS
(206) 768-0129
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDf Activities: Not reported
Violation Status: No violations found

CO395
WNW
1/2-1
5009 ft.
Lower

WG CLARK CONSTRUCTION OCCIDENTAL AVE
7958 OCCIDENTAL AVE S
SEATTLE, WA 98108

FINDS

1005127374
000009370048

Site 2 of 3 in cluster CO

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WG CLARK CONSTRUCTION OCCIDENTAL AVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1005127374

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CN396
SW
1/2-1
5019 ft.
Higher

SELLAND AUTO TRANSPORT, INC
615 S 96TH ST
SEATTLE, WA 98108

UST U003025928
CSCSL N/A
LUST

Site 4 of 6 in cluster CN

SHWS:

Facility ID: 37752719

Responsible Unit: NW

Latitude: 47 31 1

Longitude: 122 19 34

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media:

Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics:

Not reported

Halogenated Organic Compounds:

Not reported

Horizontal Collection Method:

99

EPA Priority Pollutants - Metals and Cyanide:

Not reported

Metals - Other non-priority pollutant metals:

Not reported

Polychlorinated biPhenyls (PCBs):

Not reported

Pesticides:

Not reported

Petroleum Products:

Confirmed above MTCA cleanup levels

Phenolic Compounds:

Not reported

Non-Halogenated Solvents:

Not reported

Dioxin:

Not reported

Polynuclear Aromatic Hydrocarbons (PAH):

Not reported

Reactive Wastes:

Not reported

Corrosive Wastes:

Not reported

Radioactive Wastes:

Not reported

Asbestos:

Not reported

Conventional Contaminants, Organic:

Not reported

Conventional Contaminants, Inorganic:

Not reported

Facility ID: 37752719

Responsible Unit: NW

Latitude: 47 31 1

Longitude: 122 19 34

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media:

Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SELLAND AUTO TRANSPORT, INC (Continued)

U003025928

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Not reported
Horizontal Collection Method:	99
EPA Priority Pollutants - Metals and Cyanide:	Not reported
Metals - Other non-priority pollutant metals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Confirmed above MTCA cleanup levels
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

LUST:

Facility ID:	12618	Ecology Region:	North Western
Release ID:	514116	Release Date:	6/30/1999 00:00:00
Release Status:	Cleanup Started	Status Date:	9/29/1998 00:00:00
Alternate Name:	SELLAND AUTO TRANSPORT		
Affected Media:	Soil		

Facility ID:	12618	Ecology Region:	North Western
Release ID:	514116	Release Date:	6/30/1999 00:00:00
Release Status:	Cleanup Started	Status Date:	9/29/1998 00:00:00
Alternate Name:	SELLAND AUTO TRANSPORT		
Affected Media:	Ground Water		

UST:

Facility ID:	12618
Install Date:	Not reported
Capacity:	1,101 TO 2,000 GALLONS
Status:	Not reported
Tank Name:	USED OIL/WASTE OIL
Substance:	NW
Compartment #:	Not reported
Ecology Region:	1

Facility ID:	12618
Install Date:	Not reported
Capacity:	1,101 TO 2,000 GALLONS
Status:	Not reported
Tank Name:	USED OIL/WASTE OIL
Substance:	NW
Compartment #:	Not reported
Ecology Region:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SELLAND AUTO TRANSPORT, INC (Continued)

U003025928

Facility ID: 12618
Install Date: 8/1/1979 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 12618
Install Date: 8/1/1979 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

**CN397
SW
1/2-1
5019 ft.
Higher**

**SELLAND AUTO TRANSPORT
615 S. 96TH ST.
SEATTLE, WA 98108**

**WA ICR 1001819782
N/A**

Site 5 of 6 in cluster CN

WA ICR:

Date Ecology Received Report: 01/19/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-12
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/30/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-19
County Code: 17
Contact: Not reported
Report Title: Not reported

**CN398
SW
1/2-1
5019 ft.
Higher**

**SELLAND AUTO TRANSPORT
615 S 96TH ST
SEATTLE, WA 98108**

**FINDS 1004614474
110005365265**

Site 6 of 6 in cluster CN

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SELLAND AUTO TRANSPORT (Continued)

1004614474

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CP399 DUWAMISH CO 070952
NNW 7000 E MARGINAL WAY
1/2-1 SEATTLE, WA 98108
5019 ft.
Lower

UST U001126370
CSCSL N/A

Site 1 of 2 in cluster CP

SHWS:

Facility ID: 2117
Responsible Unit: NW
Latitude: 47 32 1
Longitude: 122 18 42
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Surface Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations
or manufacturing processes, certain contaminants are suspected to be present at the
site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2117
Responsible Unit: NW
Latitude: 47 32 1
Longitude: 122 18 42
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Sediments
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations
or manufacturing processes, certain contaminants are suspected to be present at the
site
Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

DUWAMISH CO 070952 (Continued)

U001126370

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Not reported
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant medals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Not reported
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Suspected to be present
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

UST:

Facility ID: 10481
Install Date: 1/1/1962 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10481
Install Date: 1/1/1969 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10481
Install Date: 1/10/1992 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CP400 USWCOM SEATTLE DUWAMISH CO
NNW 7000 E MARGINAL WAY S
1/2-1 SEATTLE, WA 98108
5019 ft.
Lower Site 2 of 2 in cluster CP

RCRIS-SQG 1000179500
FINDS WAT540012812

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

USWCOM SEATTLE DUWAMISH CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000179500

RCRIS:

Owner: US WEST COMMUNICATIONS INC
(360) 555-1212
EPA ID: WAT540012812
Contact: EMMA HOPE
(253) 859-6505

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CO401
WNW
1/2-1
5033 ft.
Lower

INTERNATIONAL LUBRICANTS INC
7930 OCCIDENTAL S
SEATTLE, WA 98108

RCRIS-SQG 1001031696
FINDS WAR000004085

Site 3 of 3 in cluster CO

RCRIS:

Owner: INTERNATIONAL LUBRICANTS INC
(206) 762-5343
EPA ID: WAR000004085
Contact: BLAINE RHODES
(206) 762-5343

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CQ402
NW
1/2-1
5056 ft.
Lower

SOUTH PARK TRUCK TRAILER REP
7265 2ND AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000838505
FINDS WAD988512919

Site 1 of 4 in cluster CQ

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SOUTH PARK TRUCK TRAILER REP (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000838505

RCRIS:

Owner: SOUTH PARK TRUCK TRAILER REPAIR
(360) 555-1212
EPA ID: WAD988512919
Contact: WENDY CULVER
(206) 767-2974

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CR403
SW
1/2-1
5068 ft.
Higher

SEATTLE HOUSING AUTHORITY 4TH AVE
9400 4TH AVE S
SEATTLE, WA 98108

FINDS 1005102151
000009061286

Site 1 of 2 in cluster CR

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CR404
SW
1/2-1
5068 ft.
Higher

SEATTLE HOUSING AUTHORITY 4TH AVE
9400 4TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1001820286
WAH000009456

Site 2 of 2 in cluster CR

RCRIS:

Owner: SEATTLE HOUSING AUTHORITY
(206) 615-3300
EPA ID: WAH000009456
Contact: LORRIE HARRIS JERRY CHASE
(206) 545-1023

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	2957.00	D018	2957.00
D035	2957.00	F003	2957.00
F005	2957.00		

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SEATTLE HOUSING AUTHORITY 4TH AVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

Violation Status: No violations found

1001820286

CS405
West
1/2-1
5074 ft.
Lower

NW ENVIROSERVICE TRANSFER FACILITY
8105 1ST AVE. S.
SEATTLE, WA 98108

WA ICR S104484594
N/A

Site 1 of 5 in cluster CS

WA ICR:

Date Ecology Received Report: 03/28/1997
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Spill
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 95-02
County Code: 17
Contact: Not reported
Report Title: Not reported

CS406
West
1/2-1
5074 ft.
Lower

NORTHWEST ENVIROSERVICE 2
8105 1ST AVE S
SEATTLE, WA 98108

CSCSL S101703219
N/A

Site 2 of 5 in cluster CS

SHWS:

Facility ID: 2536
Responsible Unit: NW
Latitude: 47 31 54
Longitude: 122 20 7

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Suspected to be present

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Suspected to be present

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTHWEST ENVIROSERVICE 2 (Continued)

EDR ID Number
EPA ID Number

Database(s)

S101703219

Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2536
Responsible Unit: NW
Latitude: 47 31 54
Longitude: 122 20 7

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

CS407 NW ENVIROSERVICE 1ST AVE SITE
West 8105 1ST AVE S
1/2-1 SEATTLE, WA 98106
5074 ft.
Lower Site 3 of 5 in cluster CS

RCRIS-SQG 1000839143
FINDS WAD988519831

RCRIS:
Owner: NW ENVIROSERVICE 1ST AVE SITE
EPA ID: WAD988519831
Contact: WENDEE COOK
(206) 768-3238

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NW ENVIROSERVICE 1ST AVE SITE (Continued)

EDR ID Number
EPA ID Number

Database(s)

Violation Status: No violations found

1000839143

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Biennial Reporting System (BRS)

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CQ408
NW
1/2-1
5076 ft.
Lower
KELLY RYAN INC SOUTH PARK
7235 2ND AVE S
SEATTLE, WA 98108
Site 2 of 4 in cluster CQ

FINDS 1005099035
000009023116

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

CQ409
NW
1/2-1
5076 ft.
Lower
KELLY RYAN INC SOUTH PARK
7235 2ND AVE S
SEATTLE, WA 98108
Site 3 of 4 in cluster CQ

RCRIS-SQG 1001600420
WA0000981746

RCRIS:

Owner: KELLY RYAN INC SOUTH PARK

EPA ID: WA0000981746

Contact: JACK PAGE
(206) 786-2745

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

CS410
West
1/2-1
5078 ft.
Lower
PATENT CONSTRUCTION SYSTEMS
8111 1ST AVE S
SEATTLE, WA 98108
Site 4 of 5 in cluster CS

RCRIS-SQG 1000891871
FINDS WA0000181958

RCRIS:

Owner: PATENT CONSTRUCTION SYSTEMS
(360) 555-1212

EPA ID: WA0000181958

Contact: LEN WELBORN
(206) 767-0210

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PATENT CONSTRUCTION SYSTEMS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000891871

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CQ411
NW
1/2-1
5082 ft.
Lower

BJ TRUCK WRECKING
7225 2ND AVE S
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000891932
WA0000230342

Site 4 of 4 in cluster CQ

RCRIS:

Owner: BJ TRUCK WRECKING
(360) 555-1212

EPA ID: WA0000230342

Contact: LLOYD CROUSE
(360) 854-1176

Classification: N, Conditionally Exempt Small Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CS412
West
1/2-1
5084 ft.
Lower

MAGNETIC & PENETRANT SERVICES CO INC
8135 1ST AVE S
SEATTLE, WA 98108

FINDS
RCRIS-LQG
CA HAZNET

1000474167
WAD988482659

Site 5 of 5 in cluster CS

RCRIS:

Owner: DAN MILETTE
(206) 762-5855

EPA ID: WAD988482659

Contact: RICK REESE
(206) 762-5855

Classification: N, Large Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	62632.00	D002	306000.00
D004	18500.00	D005	18500.00
D007	381747.00	D008	80747.00
D011	10600.00	D018	5815.00
D035	51647.00	D039	5815.00
D040	5815.00	F003	44132.00

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Database(s)

MAGNETIC & PENETRANT SERVICES CO INC (Continued)

1000474167

F005 38232.00 F019 10600.00

Violation Status: Violations exist

Regulation Violated: -200(1)(c)(d)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -200(2)(c)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -200(1)(b) & -630(7)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -070(3)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -070(7)(c)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -200(1)(e) & -320(1)(2)abd(3)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -200(1)(e) & -330(2)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

Regulation Violated: -145(2)(a)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MAGNETIC & PENETRANT SERVICES CO INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000474167

Penalty Type: Not reported
Regulation Violated: -070(6)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1998
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/1998
Penalty Type: Not reported

There are 9 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/18/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/18/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/20/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/28/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/19/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/18/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/18/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	12/18/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	01/13/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

HAZNET:

Gepaid: WAD988482659
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .4000
Category: Liquids with pH <UN-> 2 with metals
Disposal Method: Recycler
Contact: DANIEL/VIRGINIA MILETTE
Telephone: (206) 762-5855
Mailing Address: 8135 1ST AVE S
SEATTLE, WA 98108 - 4202
County 99
Gepaid: WAD988482659
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .6000
Category: Liquids with pH <UN-> 2 with metals
Disposal Method: Treatment, Incineration
Contact: DANIEL/VIRGINIA MILETTE
Telephone: (206) 762-5855
Mailing Address: 8135 1ST AVE S
SEATTLE, WA 98108 - 4202
County 99

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MAGNETIC & PENETRANT SERVICES CO INC (Continued)

1000474167

Gepaid: WAD988482659
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .5000
Category: Liquids with nickel > 134 mg/l
Disposal Method: Recycler
Contact: DANIEL/VIRGINIA MILETTE
Telephone: (206) 762-5855
Mailing Address: 8135 1ST AVE S
 SEATTLE, WA 98108 - 4202
County 99

Gepaid: WAD988482659
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .6000
Category: Liquids with chromium (VI) > 500 mg/l
Disposal Method: Recycler
Contact: DANIEL/VIRGINIA MILETTE
Telephone: (206) 762-5855
Mailing Address: 8135 1ST AVE S
 SEATTLE, WA 98108 - 4202
County 99

Gepaid: WAD988482659
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .4000
Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method: Recycler
Contact: DANIEL/VIRGINIA MILETTE
Telephone: (206) 762-5855
Mailing Address: 8135 1ST AVE S
 SEATTLE, WA 98108 - 4202
County 99

The CA HAZNET database contains 31 additional records for this site.
Please contact your EDR Account Executive for more information.

CT413 STANDARD STEEL FABRICATING CO INC
West 8155 1ST AVE SO
1/2-1 SEATTLE, WA 98108
5097 ft.
Lower Site 1 of 3 in cluster CT

UST U001122381
N/A

UST:
 Facility ID: 1527
 Install Date: 12/31/1964 0:00
 Capacity: 111 to 1,100 Gallons
 Status: Not reported
 Tank Name: LEADED GASOLINE
 Substance: NW
 Compartment #: Not reported
 Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site
Database(s)
EDR ID Number
EPA ID Number

CT414
West
1/2-1
5097 ft.
Lower

8155 1ST AVE S
SEATTLE, WA

Site 2 of 3 in cluster CT

WA SPILL:

Facility ID: 524203
Date Received: 02/08/2002
Business Name: Not reported
Material Desc : PETROLEUM - DIESEL FUEL
Medium: ROADWAY-PAVED
Material Qty: 2
Material Units: GALLON

SPILLS S105400355
N/A

CT415
West
1/2-1
5097 ft.
Lower

STANDARD STEEL FABRICATING CO INC
8155 1ST AVE S
SEATTLE, WA 98108

Site 3 of 3 in cluster CT

RCRIS:

Owner: STANDARD STEEL FAB CO INC
(360) 555-1212
EPA ID: WA0000016154
Contact: WILLIAM DUTHIE
(206) 767-3314

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

RCRIS-SQG 1000878330
FINDS WA0000016154

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CU416
West
1/2-1
5104 ft.
Lower

TW EXPRESS
7901 1ST AVE
SEATTLE, WA 98108

Site 1 of 5 in cluster CU

RCRIS:

Owner: TW EXPRESS
(360) 555-1212
EPA ID: WAD980974588
Contact: DAVIS VICTOR
(206) 763-2858

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

RCRIS-SQG 1000113617
FINDS WAD980974588

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

TW EXPRESS (Continued)

1000113617

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CU417
West
1/2-1
5104 ft.
Lower

RECYCLE AMERICA
7901 1ST AVE S CLEAN UP
SEATTLE, WA 98108

RCRIS-SQG **1000199746**
FINDS **WAD988470365**

Site 2 of 5 in cluster CU

RCRIS:

Owner: WA ECY

(360) 555-1212

EPA ID: WAD988470365

Contact: DAVE DAVIDSON

(360) 867-7213

Classification: Small Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CU418
West
1/2-1
5104 ft.
Lower

WASTE MANAGEMENT OF SEATTLE
7901 1ST AVE S
SEATTLE, WA 98146

UST **U001126279**
LUST **N/A**

Site 3 of 5 in cluster CU

LUST:

Facility ID: 10291

Release ID: 444242

Release Status: Cleanup Started

Alternate Name: RECYCLE AMERICA

Affected Media: Soil

Ecology Region: North Western

Release Date: 12/19/1997 00:00:00

Status Date: 9/2/1997 00:00:00

Facility ID: 10291

Release ID: 444242

Release Status: Cleanup Started

Alternate Name: RECYCLE AMERICA

Affected Media: Ground Water

Ecology Region: North Western

Release Date: 12/19/1997 00:00:00

Status Date: 9/2/1997 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WASTE MANAGEMENT OF SEATTLE (Continued)

U001126279

UST:

Facility ID: 10291
Install Date: 6/1/1983 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10291
Install Date: 6/1/1983 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CU419 RECYCLE AMERICA
West 7901 1ST AVE. S.
1/2-1 SEATTLE, WA 98146
5104 ft.
Lower Site 4 of 5 in cluster CU

WA ICR S104485384
N/A

WA ICR:
Date Ecology Received Report: 11/24/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-13
County Code: 17
Contact: Not reported
Report Title: Not reported

CU420 WASTE MANAGEMENT OF SEATTLE 1ST AVE
West 7901 1ST AVE S
1/2-1 SEATTLE, WA 98108
5104 ft.
Lower Site 5 of 5 in cluster CU

RCRIS-SQG 1000121630
FINDS WAD981767221

RCRIS:
Owner: AVL FREIGHT SVC
(360) 555-1212
EPA ID: WAD981767221
Contact: JOE LETOURNEAU
(206) 763-3034
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WASTE MANAGEMENT OF SEATTLE 1ST AVE (Continued)

1000121630

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

**421
NNE
1/2-1
5122 ft.
Higher**

**COLLINS AVIATION
6660 PERIMETER RD S BOEING FLD
SEATTLE, WA 98108**

**RCRIS-SQG 1000286257
FINDS WAD131467912**

RCRIS:

Owner: COLLINS AVIATION
(360) 555-1212

EPA ID: WAD131467912

Contact: STEVE ANDERSON
(206) 767-4150

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDf Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

**422
NNW
1/2-1
5132 ft.
Lower**

**DNR
6715,6737 CORSON AVE. S. 6800 E. MARGINAL WAY S.
SEATTLE, WA 98108**

**WA ICR S102513742
N/A**

WA ICR:

Date Ecology Received Report: 07/27/1990
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 90-08
County Code: 17
Contact: Not reported
Report Title: Not reported

**CV423
NW
1/2-1
5139 ft.
Lower**

**500 S MYRTLE ST
SEATTLE, WA
Site 1 of 3 in cluster CV**

**SPILLS S105387832
N/A**

WA SPILL:

Facility ID: 501593
Date Received: 12/20/1998

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S105387832

Business Name: CONSTRUCTION
Material Desc : PETROLEUM - FUEL OIL
Medium: SURFACE WATER-MARINE
Material Qty: 2
Material Units: EACH

CV424
NW
1/2-1
5139 ft.
Lower

ALL ALASKAN SEAFOODS INC
501 S MYRTLE ST
SEATTLE, WA 98108

RCRIS-SQG 1000891916
FINDS WA0000229062

Site 2 of 3 in cluster CV

RCRIS:

Owner: MANSON CONSTRUCTION
(360) 555-1212

EPA ID: WA0000229062

Contact: JEFF DEBELL
(206) 285-8200

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CV425
NW
1/2-1
5139 ft.
Lower

SEATTLE BOILER WORKS, INC.
500 SOUTH MYRTLE ST.
SEATTLE, WA 98108

UST U003028374
N/A

Site 3 of 3 in cluster CV

UST:

Facility ID: 8147
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

CW426
WNW
1/2-1
5192 ft.
Lower

EASTERN SUPPLY CO
7745 1ST AVE S
SEATTLE, WA 98108

CSCSL S100079784
N/A

Site 1 of 2 in cluster CW

SHWS:

Facility ID: 2258
Responsible Unit: NW
Latitude: 47 31 57
Longitude: 122 20 18
Ecology Site Status relative to the MTCA cleanup process:
Remedial Action in progress

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EASTERN SUPPLY CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

S100079784

CX427
ENE
1/2-1
5193 ft.
Higher

THAW CORP
8300 MILITARY RD S
SEATTLE, WA 98108

FINDS **1004990905**
000007559870

Site 1 of 2 in cluster CX

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

CX428
ENE
1/2-1
5193 ft.
Higher

THAW CORP
8300 MILITARY RD S
SEATTLE, WA 98108

RCRIS-SQG **1001234046**
WAH000004580

Site 2 of 2 in cluster CX

RCRIS:

Owner: REI
(253) 395-3780
EPA ID: WAH000004580
Contact: RICK GIBBS
(206) 505-2110

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

CW429
WNW
1/2-1
5197 ft.
Lower

LAIDLAW
7739 1ST AVE S
SEATTLE, WA 98108

RCRIS-SQG **1000189945**
FINDS **WAD980836001**
UST
CSCSL
WA ICR
HSL
SPILLS

Site 2 of 2 in cluster CW

RCRIS:

Owner: LAIDLAW TRANSIT INC
(360) 555-1212
EPA ID: WAD980836001
Contact: JOHN JORDAN
(206) 764-9700

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

LAIDLAW (Continued)

1000189945

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 2320

Responsible Unit: NW

Latitude: 47 31 53

Longitude: 122 20 7

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Final Independent Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

4 - Moderate to lowest assessed risk to human health and to the environment

Affected Media: Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Confirmed above MTCA cleanup levels

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Not reported

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Facility ID: 2320

Responsible Unit: NW

Latitude: 47 31 53

Longitude: 122 20 7

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Final Independent Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

4 - Moderate to lowest assessed risk to human health and to the environment

Affected Media: Soil

Media Status: R (Remediated) - Contaminants have been treated, removed, or contained to meet cleanup levels established for the site. (This status determination may only be made by Ecology

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

LAIDLAW (Continued)

1000189945

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Treated, removed, or contained
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Not reported
Metals - Other non-priority pollutant metals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Treated, removed, or contained
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

WA SPILL:

Facility ID:	428630
Date Received:	01/30/1998
Business Name:	LAIDLAW TRANSIT
Material Desc :	PETROLEUM - DIESEL FUEL
Medium:	SOIL
Material Qty:	5
Material Units:	GALLON

WA HSL:

Rank :	4
Facility Status :	Independent RA
Facility Type :	Not reported

WA ICR:

Date Ecology Received Report:	08/16/1999
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Not reported
Site Register Issue:	98-17
County Code:	17
Contact:	Not reported
Report Title:	Not reported

UST:

Facility ID:	12778
Install Date:	12/31/1964 0:00
Capacity:	111 to 1,100 Gallons
Status:	Not reported
Tank Name:	USED OIL/WASTE OIL
Substance:	NW
Compartment #:	Not reported
Ecology Region:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

LAILAW (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000189945

Facility ID: 12778
Install Date: 10/30/1989 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 12778
Install Date: 10/30/1989 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

430
WNW
1/2-1
5276 ft.
Lower

1ST KENYON DRUM
1ST AVE S & SW KENYON ST
SEATTLE, WA 98106

RCRIS-SQG 1000455943
FINDS WAD988476073

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD988476073
Contact: PAUL OBRIEN
(360) 867-7130

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
COOS BAY	96500318	60 MILES SOUTH OF COOS BAY 1.5 MIL	60 MILES SOUTH OF COOS BAY 1.5	98101	ERNS
CORDOVA	1000155598	COPPER RIVER RR YARD	LOTS 9 8 BLOCK 6 ODIK PARK SU	98108	PADS, WA ICR
SEATTLE	94370787	WEST OF BALLARD BRIDGE SHIP CANAL	WEST OF BALLARD BRIDGE SHIP CA	98101	ERNS
SEATTLE	90172172	NO. 1 SOUTH IDAHO STREET	NO. 1 SOUTH IDAHO STREET		ERNS
SEATTLE	96482089	SOUTH 115TH STREET AND E. MARGINAL	SOUTH 115TH STREET AND E. MARG		ERNS
SEATTLE	93305891	16TH SOUTH	16TH SOUTH		ERNS
SEATTLE	90165318	16TH AVE S. BRIDGE ON THE DUWAMISH	16TH AVE S. BRIDGE ON THE DUWA		ERNS
SEATTLE	2000530534	46TH AVE SOUTH	46TH AVE SOUTH		ERNS
SEATTLE	1004644099	PRESERVATIVE PAINT CO	5400 TO 5410 AIRPORT WAY S	98108	FTTS
SEATTLE	S103506798	EVERGREEN MARINE LEASING THREE RE	7310 - 7350 8TH AVE. S.	98108	WA ICR
SEATTLE	1004793782	GLOBAL INTERMODAL SYSTEMS	1818 S 93RD ST	98108	RCRIS-SQG
SEATTLE	1004793884	AHRENIUS MANUFACTURING INC	1425 S 93RD	98108	RCRIS-SQG
SEATTLE	1004793475	CLARKLIFT OF WASHINGTON ALASKA INC	1313 S 96TH ST	98108	RCRIS-SQG, FINDS
SEATTLE	1004794131	SELLAND AUTO TRANSPORT	615 S 96TH ST	98108	RCRIS-SQG
SEATTLE	S104223669	SR 99 FIRST AVE. BRIDGE SPILLAWS	SR 99 FIRST AVE. BRIDGE		WA ICR
SEATTLE	93335341	ACROSS STREET FROM 7600 5TH AVENUE	ACROSS STREET FROM 7600 5TH AV		ERNS
SEATTLE	1001490824	SEATTLE CITY ENG DEPT AIRPORT WAY	AIRPORT WAY S & DAWSON ST S	98108	RCRIS-SQG, FINDS
SEATTLE	90182764	ALLEY BTWN. 52ND & SEWARD PARK	ALLEY BTWN. 52ND & SEWARD PARK		ERNS
SEATTLE	99617128	NORTH AND SOUTH SIDE OF MCNIEL ISL	NORTH AND SOUTH SIDE OF MCNIEL		ERNS
SEATTLE	S103510367	UNION PACIFIC RAILROAD	4TH S. AND DAWSON	98108	WA ICR
SEATTLE	1004794302	MACHINISTS INC PLANT 2	509 S AUSTIN ST	98108	RCRIS-SQG
SEATTLE	8854741	8TH AVE SOUTH & EAST MARGINAL WAY.	8TH AVE SOUTH & EAST MARGINAL		ERNS
SEATTLE	1004793341	FRUEHAUF TRAILER INC SEATTLE	9426 8TH AVE S	98108	RCRIS-SQG, FINDS
SEATTLE	1004793352	TIERNEY ELECTRICAL MFG CO	7901 7TH AVE S	98108	RCRIS-SQG
SEATTLE	1004793597	ALPINE EQUIPMENT RENTALS & SUPPLY	5421 1ST AVE S	98108	RCRIS-SQG
SEATTLE	1004793844	PHILS FINISHING TOUCH	7401 8TH AVE S	98108	RCRIS-SQG, FINDS
SEATTLE	1004793961	WESTEC INDUSTRIES INC	8111 7TH AVE S	98108	RCRIS-SQG
SEATTLE	1004794180	WARNERS FOREIGN AUTO REPAIR	9001 14TH AVE S	98108	RCRIS-SQG, FINDS
SEATTLE	1004794233	PSF MECHANICAL INC	9322 14TH AVE S	98108	RCRIS-SQG
SEATTLE	1004794243	PSF INDUSTRIES INC FIELD YARD	9332 14TH AVE S	98108	RCRIS-SQG
SEATTLE	1004794574	BIG JOHNS TRUCK REPAIR INC	6533 3RD AVE S	98108	RCRIS-SQG
SEATTLE	1004794920	NORTHLAND SERVICES INC TRANSFER FA	7400 8TH AVE S TRANSFER FACILI	98108	RCRIS-SQG
SEATTLE	1004795090	DESIGN DIRECT SOUND INC	9320 15TH AVE S UNITS C-E	98108	RCRIS-SQG
SEATTLE	1004795137	FEDERAL EXPRESS CORP BFI	9320 15TH AVE S	98108	RCRIS-SQG
SEATTLE	1004793133	CAMERAS WEST 1032	1908 4TH AVE	98101	RCRIS-SQG
SEATTLE	1004794814	SEATTLE CITY DEXTER HORTON BUILDIN	710 2ND AVE	98101	RCRIS-SQG
SEATTLE	1004795029	WASHINGTON MUTUAL BANK	1101 2ND AVE	98101	RCRIS-SQG
SEATTLE	2000529392	2300 26TH AVE. SOUTH	2300 26TH AVE. SOUTH		ERNS
SEATTLE	2000670411	AVE. PARK	AVE. PARK		ERNS
SEATTLE	S103508429	NORTHWEST ENVIRO SERVICE	1ST AVE. S.	98108	WA ICR
SEATTLE	S104484977	MOBIL CANAL BULK PLANT	4401 11TH AVE. NW	98108	WA ICR
SEATTLE	92261246	BALLARD BRIDGE	BALLARD BRIDGE		ERNS
SEATTLE	90165315	BALLARD BRIDGE	BALLARD BRIDGE		ERNS

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SEATTLE	98424390	BALLARD BRIDGE	BALLARD BRIDGE		ERNS
SEATTLE	90182811	BETWEEN GASWORKS PARK & FREEMONT B	BETWEEN GASWORKS PARK & FREEMONT B		ERNS
SEATTLE	93330461	5900 BLOCK SEAVIEW AVE 200 YDS SOU	5900 BLOCK SEAVIEW AVE 200 YDS		ERNS
SEATTLE	93349116	520 BRIDGE, EAST HIGH RISE, ALONG	520 BRIDGE, EAST HIGH RISE, AL		ERNS
SEATTLE	96482126	BUILDING SOUTH OF WESTLAKE TOWER O	BUILDING SOUTH OF WESTLAKE TOW		ERNS
SEATTLE	1004793660	ROCKWELL AUTOMATION DODGE CST	500 S CHICAGO ST	98108	RCRIS-SQG
SEATTLE	1001490689	CLOVERDALE BUSINESS PARK	309 S CLOVERDALE D21		RCRIS-SQG, FINDS
SEATTLE	1004794317	CHRISTIAN BROTHERS FLOOR SVC INC	309 S CLOVERDALE STE C20	98108	RCRIS-SQG
SEATTLE	1005114392	EUROIMPORT CO INC	309 S CLOVERDALE ST BLDG D41	98108	FINDS, FTTS
SEATTLE	92274977	COLMAN PARK -3400 HOLGATE (GO EAST	COLMAN PARK -3400 HOLGATE (GO		ERNS
SEATTLE	1001491008	1ST AVE BRG BBC2	NE COR S MICHIGAN ST & 1ST AVE	98108	RCRIS-SQG, FINDS
SEATTLE	S103508792	RASMUSSEN EQUIPMENT	415 S. COVERDALE ST.	98108	WA ICR
SEATTLE	1004794412	SOUTH PARK MARINA	8604 DALLAS AVE S	98108	RCRIS-SQG, FINDS
SEATTLE	1001234015	NORTHWEST ANTIFREEZE SVC INC	8661A DALLAS AVE S	98108	RCRIS-SQG
SEATTLE	99640180	402 SOUTH DAWSON ST PHONE NO.(206)	402 SOUTH DAWSON ST PHONE NO.(ERNS
SEATTLE	1003880504	BOEING COMPANY N FIELD SEATTLE CY	ELLIS AV & WILLOW ST INTERSECT		CERC-NFRAP
SEATTLE	S103504475	SEATTLE CITY LIGHT/N. BOEING FIELD	ELLIS AVE. S. ADJACENT TO BOEI	98108	WA ICR
SEATTLE	2000537810	SOUTH END OF SEA VIEW AVENUE	SOUTH END OF SEA VIEW AVENUE		ERNS
SEATTLE	92270019	ON FAIRVIEW BETWEEN EASTLAKE AND W	ON FAIRVIEW BETWEEN EASTLAKE A		ERNS
SEATTLE	98425296	1515 FAIRVIEW EAST SOUTH PIER	1515 FAIRVIEW EAST SOUTH PIER		ERNS
SEATTLE	94359799	8105 FIRST AVE SOUTH	8105 FIRST AVE SOUTH		ERNS
SEATTLE	90179880	FISHERMANS TERMINAL/ BY BRIDGE	FISHERMANS TERMINAL/ BY BRIDGE		ERNS
SEATTLE	93350596	FREEMONT BRIDGE FREEMONT BLVD	FREEMONT BRIDGE FREEMONT BLVD		ERNS
SEATTLE	99648239	HARBOR ISLAND CORPORATE PARK / 100	HARBOR ISLAND CORPORATE PARK /		ERNS
SEATTLE	S103503667	BAXTER RUTHERFORD	911 S. HOSMER ST.	98108	WA ICR
SEATTLE	8854078	INST 5 SOUTHBOUND WHERE DUWAMISH R	INST 5 SOUTHBOUND WHERE DUWAMI		ERNS
SEATTLE	1004793616	GLITSA AMERICAN INC	327 S KENYON ST	98108	RCRIS-SQG
SEATTLE	S103505624	BOEING - NORTH FIELD - FIRE TRAINI	KING COUNTY AIRPORT	98108	WA ICR
SEATTLE	1004793581	CLYDE WEST INC	9615 W MARGINAL WAY S	98108	RCRIS-SQG, FINDS
SEATTLE	1004794452	ARCO 5218 PSI 0685	7200 E MARGINAL WAY S	98108	RCRIS-SQG, FINDS
SEATTLE	S104584304	BOEING A&M DEVELOPMENT CENTER	9725 E MARGINAL WAY S	98108	HAZNET
SEATTLE	S104971554	ATLAS DEMOLITION	9800 E MARGINAL WAY S	98108	CSCSL NFA
SEATTLE	1003880338	DIMENSIONAL ENGINEERING	9407 E MARGINAL WY	98108	CERC-NFRAP
SEATTLE	1003880489	SEATTLE, CY OF, 1ST AV BRG LDFL	E MARGINAL WY S & FIDALGO ST	98108	CERC-NFRAP
SEATTLE	S103505620	BOEING - NORTH BOEING FIELD	E. MARGINAL WAY	98108	WA ICR
SEATTLE	S105124713	MUSEUM OF FLIGHT PROPERTY	9404 E. MARGINAL WAY S.	98108	WA ICR
SEATTLE	U003800972	MUSEUM OF FLIGHT PROPERTY	9404 E MARGINAL WAY S	98108	UST, LUST, SPILLS
SEATTLE	2000516700	MILITARY ROAD SOUTH UNDER	MILITARY ROAD SOUTH UNDER		ERNS
SEATTLE	S103512420	TRITELL LLC	1821 1823 MINOR AVE.	98101	WA ICR
SEATTLE	1004614738	SEATTLE CITY LIGHT SANISLO SCHOOL	1812 SW MYRTLE	98108	FINDS, FTTS
SEATTLE	90165319	NEAR AURORA BRIDGE	NEAR AURORA BRIDGE		ERNS
SEATTLE	2000533571	NOREAST SIDE OF BALLARD BRIDGE	NOREAST SIDE OF BALLARD BRIDGE		ERNS
SEATTLE	98463964	NORTHLAKE SHIPYARD EAST SIDE 190 B	NORTHLAKE SHIPYARD EAST SIDE I		ERNS
SEATTLE	99627447	OCEAN BEAUTY DOCK JUST E OF BALLAR	OCEAN BEAUTY DOCK JUST E OF BA		ERNS
SEATTLE	91217897	SOUTH OF 19548 15TH AV NE IN SEATT	SOUTH OF 19548 15TH AV NE IN S		ERNS
SEATTLE	1001490189	ETT X RAY INCORPORATED	7500 PERIMETER RD BOEING FLD	98108	RCRIS-SQG, FINDS
SEATTLE	1004793831	NORDSTROM INC	7979 PERIMETER RD S	98108	RCRIS-SQG, FINDS

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SEATTLE	1004794169	GALVIN FLYING SERVICE INC	7149 PERIMETER RD S	98108	RCRIS-SQG
SEATTLE	1004794592	UPS BOEING FIELD	7575 PERIMETER RD S	98108	RCRIS-SQG
SEATTLE	U000592476	FORREST TAYLOR	6505 PERIMETER RD BOEING FIELD	98108	UST
SEATTLE	92252700	PIER 5 SOUTH	PIER 5 SOUTH		ERNS
SEATTLE	92269158	PIONEER BUILDERS 98TH AT PACIFIC H	PIONEER BUILDERS 98TH AT PACIF		ERNS
SEATTLE	1004793912	RS HUGHES CO INC	6530 5TH PL S	98108	RCRIS-SQG, FINDS
SEATTLE	93301317	17 PLACE AVE SOUTH NEAR HWY 99	17 PLACE AVE SOUTH NEAR HWY 99		ERNS
SEATTLE	91241651	PLANT 2 16TH AVE. BRIDGE, DUWAMISH	PLANT 2 16TH AVE. BRIDGE, DUWA		ERNS
SEATTLE	S103508959	SEATAC AIRPORT - PAN AM HANGER	PORT OF SEATTLE	98108	WA ICR
SEATTLE	876643	SALMON BAY BALLARD BRIDGE	SALMON BAY BALLARD BRIDGE		ERNS
SEATTLE	1004614173	SEATTLE SD 1228	SEATTLE STADIUM 2600 SLO THIST	98108	FINDS, FTTS
SEATTLE	S103350801	SOUTH TS / SOUTH HHW FACILITY - MR	7800 SECOND AVENUE S		SWF/LF
SEATTLE	90151373	SOUTH SIDE OF THE CANAL ENTRANCE T	SOUTH SIDE OF THE CANAL ENTRAN		ERNS
SEATTLE	99626536	.50MI SOUTH OF PT WELLS/ .25MI OFF	.50MI SOUTH OF PT WELLS/ .25MI		ERNS
SEATTLE	2000530167	UNDER BALLARD BRIDGE	UNDER BALLARD BRIDGE		ERNS

EPA Waste Codes Addendum

Code	Description
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D004	ARSENIC
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D010	SELENIUM
D011	SILVER
D018	BENZENE
D027	1,4-DICHLOROBENZENE
D035	METHYL ETHYL KETONE
D039	TETRACHLOROETHYLENE
D040	TRICHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

EPA Waste Codes Addendum

Code	Description
	CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
F019	WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.
U228	ETHENE, TRICHLORO-
U228	TRICHLOROETHYLENE

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List

Source: EPA

Telephone: N/A

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/22/02

Date Made Active at EDR: 06/21/02

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 05/06/02

Elapsed ASTM days: 46

Date of Last EDR Contact: 05/06/02

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1

Telephone 617-918-1143

EPA Region 6

Telephone: 214-655-6659

EPA Region 3

Telephone 215-814-5418

EPA Region 8

Telephone: 303-312-6774

EPA Region 4

Telephone 404-562-8033

Proposed NPL: Proposed National Priority List Sites

Source: EPA

Telephone: N/A

Date of Government Version: 02/26/02

Date Made Active at EDR: 06/21/02

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 05/06/02

Elapsed ASTM days: 46

Date of Last EDR Contact: 05/06/02

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA

Telephone: 703-413-0223

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/12/02

Date Made Active at EDR: 06/03/02

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/25/02

Elapsed ASTM days: 70

Date of Last EDR Contact: 03/25/02

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Source: EPA

Telephone: 703-413-0223

As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/14/02
Date Made Active at EDR: 06/03/02
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/25/02
Elapsed ASTM days: 70
Date of Last EDR Contact: 03/25/02

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 800-424-9346

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/14/01
Date Made Active at EDR: 01/14/02
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 11/14/01
Elapsed ASTM days: 61
Date of Last EDR Contact: 06/10/02

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 800-424-9346

Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 04/01/02
Date Made Active at EDR: 06/21/02
Database Release Frequency: Varies

Date of Data Arrival at EDR: 05/20/02
Elapsed ASTM days: 32
Date of Last EDR Contact: 03/04/02

ERNS: Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/00
Date Made Active at EDR: 06/03/02
Database Release Frequency: Varies

Date of Data Arrival at EDR: 03/05/02
Elapsed ASTM days: 90
Date of Last EDR Contact: 04/29/02

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System

Source: EPA/NTIS

Telephone: 800-424-9346

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/99
Database Release Frequency: Biennially

Date of Last EDR Contact: 06/17/02
Date of Next Scheduled EDR Contact: 09/16/02

CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: N/A
Database Release Frequency: Varies

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

ROD: Records Of Decision

Source: EPA

Telephone: 703-416-0223

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 09/30/01
Database Release Frequency: Annually

Date of Last EDR Contact: 04/09/02
Date of Next Scheduled EDR Contact: 07/08/02

DELISTED NPL: National Priority List Deletions

Source: EPA
Telephone: N/A

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/22/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 05/06/02
Date of Next Scheduled EDR Contact: 08/05/02

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report

Source: EPA
Telephone: N/A

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/21/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 04/08/02
Date of Next Scheduled EDR Contact: 07/08/02

HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation
Telephone: 202-366-4555

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/01
Database Release Frequency: Annually

Date of Last EDR Contact: 04/22/02
Date of Next Scheduled EDR Contact: 07/22/02

MLTS: Material Licensing Tracking System

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/12/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 04/08/02
Date of Next Scheduled EDR Contact: 07/08/02

MINES: Mines Master Index File

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959

Date of Government Version: 12/14/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 04/01/02
Date of Next Scheduled EDR Contact: 07/01/02

NPL LIENS: Federal Superfund Liens

Source: EPA
Telephone: 205-564-4267

Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/15/91
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 05/28/02
Date of Next Scheduled EDR Contact: 08/26/02

PADS: PCB Activity Database System

Source: EPA

Telephone: 202-564-3887

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/01/02
Database Release Frequency: Annually

Date of Last EDR Contact: 05/14/02
Date of Next Scheduled EDR Contact: 08/12/02

RAATS: RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 06/10/02
Date of Next Scheduled EDR Contact: 09/09/02

TRIS: Toxic Chemical Release Inventory System

Source: EPA

Telephone: 202-260-1531

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/99
Database Release Frequency: Annually

Date of Last EDR Contact: 03/25/02
Date of Next Scheduled EDR Contact: 06/24/02

TSCA: Toxic Substances Control Act

Source: EPA

Telephone: 202-260-5521

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/98
Database Release Frequency: Every 4 Years

Date of Last EDR Contact: 06/10/02
Date of Next Scheduled EDR Contact: 09/09/02

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Source: EPA

Telephone: 202-564-2501

Date of Government Version: 01/14/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/25/02
Date of Next Scheduled EDR Contact: 06/24/02

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-564-2501

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/25/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/25/02
Date of Next Scheduled EDR Contact: 06/24/02

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF WASHINGTON ASTM STANDARD RECORDS

CSCSL: Confirmed & Suspected Contaminated Sites List

Source: Department of Ecology

Telephone: 360-407-7200

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 11/26/01

Date Made Active at EDR: 01/09/02

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 12/11/01

Elapsed ASTM days: 29

Date of Last EDR Contact: 05/21/02

HSL: Hazardous Sites List

Source: Department of Ecology

Telephone: 360-407-7200

The Hazardous Sites List is a subset of the CSCSL Report. It includes sites which have been assessed and ranked using the Washington Ranking Method (WARM).

Date of Government Version: 02/26/02

Date Made Active at EDR: 04/10/02

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 03/11/02

Elapsed ASTM days: 30

Date of Last EDR Contact: 06/10/02

SWF/LF: Solid Waste Facility Database

Source: Department of Ecology

Telephone: 360-407-6132

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/01/01

Date Made Active at EDR: 12/19/01

Database Release Frequency: Annually

Date of Data Arrival at EDR: 12/04/01

Elapsed ASTM days: 15

Date of Last EDR Contact: 04/09/02

LUST: Leaking Underground Storage Tanks Site List

Source: Department of Ecology

Telephone: 360-407-7200

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 03/13/02

Date Made Active at EDR: 03/29/02

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/18/02

Elapsed ASTM days: 11

Date of Last EDR Contact: 06/18/02

UST: Underground Storage Tank Database

Source: Department of Ecology

Telephone: 360-407-7170

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 03/13/02

Date Made Active at EDR: 04/08/02

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/18/02

Elapsed ASTM days: 21

Date of Last EDR Contact: 06/18/02

STATE OF WASHINGTON ASTM SUPPLEMENTAL RECORDS

CSCSL NFA: Confirmed & Contaminated Sites - No Further Action

Source: Department of Ecology

Telephone: 360-407-7170

The data set contains information about sites previously on the Confirmed and Suspected Contaminated Sites list that have received a No Further Action (NFA) determination. Because it is necessary to maintain historical records of sites that have been investigated and cleaned up, sites are not deleted from the database when cleanup activities are completed. Instead, a No Further Action code is entered based upon the type of NFA determination the site received.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 11/26/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/11/02
Date of Next Scheduled EDR Contact: 02/18/02

ICR: Independent Cleanup Reports

Source: Department of Ecology
Telephone: 360-407-7200

These are remedial action reports Ecology has received from either the owner or operator of the sites. These actions have been conducted without department oversight or approval and are not under an order or decree.

Date of Government Version: 10/31/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 05/21/02
Date of Next Scheduled EDR Contact: 08/19/02

SPILLS: Reported Spills

Source: Department of Ecology
Telephone: 360-407-7450

Spills reported to the Spill Prevention, Preparedness and Response Division.

Date of Government Version: 04/17/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 04/10/02
Date of Next Scheduled EDR Contact: 07/08/02

EMI: Washington Emissions Data System

Source: Department of Ecology
Telephone: 360-407-6040

Date of Government Version: 12/31/99
Database Release Frequency: Annually

Date of Last EDR Contact: 04/22/02
Date of Next Scheduled EDR Contact: 07/22/02

LOCAL RECORDS

KING COUNTY:

Abandoned Landfill Study in King County

Source: Seattle-King County Department of Public Health
Telephone: 206-296-4785

The King County Abandoned Landfill Survey was conducted from October through December 1984 by the Health Department's Environmental Health Division at the request of the King County Council. The primary objective of the survey was to determine if any public health problems existed at the predetermined 24 sites.

Date of Government Version: 04/30/85
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 10/21/94
Date of Next Scheduled EDR Contact: N/A

SEATTLE COUNTY:

Abandoned Landfill Study in the City of Seattle

Source: Seattle - King County Department of Public Health
Telephone: 206-296-4785

The Seattle Abandoned Landfill Survey was conducted in June and July of 1984 by the Health Department's Environmental Health Division at the request of the Mayor's Office. The primary objective of the survey was to determine if any public health problems existed at the predetermined 12 sites.

Date of Government Version: 07/30/84
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 10/21/94
Date of Next Scheduled EDR Contact: N/A

SEATTLE/KING COUNTY:

Seattle - King County Abandoned Landfill Toxicity / Hazard Assessment Project

Source: Department of Public Health
Telephone: 206-296-4785

This report presents the Seattle-King County Health Department's follow-up investigation of two city owned and four county owned abandoned landfills which was conducted from February to December 1986.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/86
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 08/14/95
Date of Next Scheduled EDR Contact: N/A

SNOHOMISH COUNTY:

Solid Waste Sites of Record at Snohomish Health District

Source: Snohomish Health District
Telephone: 206-339-5250

Date of Government Version: 01/17/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 04/24/02
Date of Next Scheduled EDR Contact: 07/22/02

TACOMA/PIERCE COUNTY:

Closed Landfill Survey

Source: Tacoma-Pierce County Health Department
Telephone: 206-591-6500

Following numerous requests for information about closed dumpsites and landfills in Pierce County, the Tacoma-Pierce County Health Department decided to conduct a study on the matter. The aim of the study was to evaluate public health risks associated with the closed dumpsites and landfills, and to determine the need, if any, for further investigations of a more detailed nature. The sites represent all of the known dumpsites and landfills closed after 1950.

Date of Government Version: 04/15/93
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 01/11/95
Date of Next Scheduled EDR Contact: N/A

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

STREET AND ADDRESS INFORMATION

© 2001 Geographic Data Technology, Inc., Rel. 07/2001. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.

GEOCHECK® - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

SOUTH PARK BRIDGE
16TH AVE SOUTH
SEATTLE, WA 98101

TARGET PROPERTY COORDINATES

Latitude (North):	47.528381 - 47° 31' 42.2"
Longitude (West):	122.314453 - 122° 18' 52.0"
Universal Transverse Mercator:	Zone 10
UTM X (Meters):	551604.8
UTM Y (Meters):	5263893.0

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided in the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good commercial or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

USGS TOPOGRAPHIC MAP ASSOCIATED WITH THIS SITE

Target Property: 2447122-E3 SEATTLE SOUTH, WA
Source: USGS 7.5 min quad index

GENERAL TOPOGRAPHIC GRADIENT AT TARGET PROPERTY

Target Property: General NW

Source: General Topographic Gradient has been determined from the USGS 1 Degree Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

<u>Target Property County</u>	<u>FEMA Flood</u>
KING, WA	<u>Electronic Data</u>
	YES - refer to the Overview Map and Detail Map
Flood Plain Panel at Target Property:	53033C0640F / CWPP
Additional Panels in search area:	53033C0645F / CWPP

NATIONAL WETLAND INVENTORY

<u>NWI Quad at Target Property</u>	<u>NWI Electronic</u>
SEATTLE SOUTH	<u>Data Coverage</u>
	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Site-Specific Hydrogeological Data*:

Search Radius: 2.0 miles
Location Relative to TP: 1/4 - 1/2 Mile NNE
Site Name: BOEING COMPANY PLANT 2
Site EPA ID Number: WAD009256819
Groundwater Flow Direction: NOT AVAILABLE
Inferred Depth to Water: 15 feet
Hydraulic Connection: The near-surface aquifer is situated in artificial fill of sand, gravel, and clay. The ground water elevation is consistent with the surface elevation of the Duwamish Waterway.
Sole Source Aquifer: No information about a sole source aquifer is available
Data Quality: Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 2.000 Miles.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

<u>MAP ID</u>	<u>LOCATION FROM TP</u>	<u>GENERAL DIRECTION GROUNDWATER FLOW</u>
1	1/4 - 1/2 Mile NNE	W
2	1/4 - 1/2 Mile North	W
3	1/2 - 1 Mile South	W
4	1/2 - 1 Mile NNW	Not Reported
5	1/2 - 1 Mile SSW	NNE
6	1/2 - 1 Mile SSE	NW
7	1 - 2 Miles NW	SW
8	1 - 2 Miles North	W
9	1 - 2 Miles NNW	WSW
A10	1 - 2 Miles NNW	SW
A11	1 - 2 Miles NNW	W
12	1 - 2 Miles NNW	W
13	1 - 2 Miles ENE	Not Reported
14	1 - 2 Miles NNW	Not Reported
15	1 - 2 Miles SE	Not Reported

For additional site information, refer to Physical Setting Source Map Findings.

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

* ©1996 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

ROCK STRATIGRAPHIC UNIT

Era: Not Reported
 System: Not Reported
 Series: Not Reported
 Code: WTER (decoded above as Era, System & Series)

GEOLOGIC AGE IDENTIFICATION

Category: Not Reported

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: ALDERWOOD

Soil Surface Texture: gravelly - sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained. Soils have a layer of low hydraulic conductivity, wet state high in the profile. Depth to water table is 3 to 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: MODERATE

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Permeability Rate (in/hr)	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	7 inches	gravelly - sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COURSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 6.00 Min: 2.00	Max: 6.50 Min: 5.10
2	7 inches	35 inches	very gravelly - loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COURSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 6.00 Min: 2.00	Max: 6.50 Min: 5.10

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Permeability Rate (in/hr)	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
3	35 inches	39 inches	cemented	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
very gravelly - sandy loam

Surficial Soil Types: silt loam
very gravelly - sandy loam

Shallow Soil Types: silt loam

Deeper Soil Types: very gravelly - coarse sand
stratified
very gravelly - sand
very gravelly - loamy sand

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of the records review (see 7.1.1), and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

<u>DATABASE</u>	<u>SEARCH DISTANCE (miles)</u>
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID

No Wells Found

WELL ID

LOCATION
FROM TP

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID

No PWS System Found

WELL ID

LOCATION
FROM TP

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID

No Wells Found

WELL ID

LOCATION
FROM TP

-
- A horizontal scale bar with a black background and white markings. It is labeled '0' at the left end, '1/2' at the midpoint, '1' at the first major tick, and '2 Miles' at the right end. The bar is divided into four equal segments by three vertical white lines.

CUSTOMER: Parsons Brinckerhoff
CONTACT: Patrick Romero
INQUIRY #: 806613.2s
DATE: June 28, 2002 10:33 am

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

1 NNE 1/4 - 1/2 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	4073 W 4 10 Not Reported 11/03/1992	AQUIFLOW	61378
2 North 1/4 - 1/2 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	5290 W 4 6.5 Not Reported 04/13/1994	AQUIFLOW	61360
3 South 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	1476 W Not Reported Not Reported 12.5 12/05/1990	AQUIFLOW	61185
4 NNW 1/2 - 1 Mile Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	4431008342 Not Reported 8.86 10.91 Not Reported Not Reported	AQUIFLOW	61033
5 SSW 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	29883936 NNE Not Reported Not Reported 11 03/02/1998	AQUIFLOW	61068
6 SSE 1/2 - 1 Mile Higher	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	2212 NW 8.7 11.0 Not Reported 04/22/1991	AQUIFLOW	61244
7 NW 1 - 2 Miles Lower	Site ID: Groundwater Flow: Shallowest Water Table Depth: Deepest Water Table Depth: Average Water Table Depth: Date:	Not Reported SW 9.52 14.10 Not Reported 12/10/1990	AQUIFLOW	61191

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
8 North 1 - 2 Miles Lower	Site ID:	4136		
	Groundwater Flow:	W	AQUIFLOW	61046
	Shallowest Water Table Depth:	Not Reported		
	Deepest Water Table Depth:	Not Reported		
	Average Water Table Depth:	10		
	Date:	11/10/1992		
9 NNW 1 - 2 Miles Lower	Site ID:	2884		
	Groundwater Flow:	WSW	AQUIFLOW	61364
	Shallowest Water Table Depth:	6.76		
	Deepest Water Table Depth:	7.55		
	Average Water Table Depth:	Not Reported		
	Date:	06/28/1991		
A10 NNW 1 - 2 Miles Lower	Site ID:	1579		
	Groundwater Flow:	SW	AQUIFLOW	61365
	Shallowest Water Table Depth:	5.3		
	Deepest Water Table Depth:	6.6		
	Average Water Table Depth:	Not Reported		
	Date:	12/23/1993		
A11 NNW 1 - 2 Miles Lower	Site ID:	309690		
	Groundwater Flow:	W	AQUIFLOW	61095
	Shallowest Water Table Depth:	6.60		
	Deepest Water Table Depth:	8.52		
	Average Water Table Depth:	Not Reported		
	Date:	06/03/1998		
12 NNW 1 - 2 Miles Lower	Site ID:	3034		
	Groundwater Flow:	W	AQUIFLOW	61254
	Shallowest Water Table Depth:	8.26		
	Deepest Water Table Depth:	9.12		
	Average Water Table Depth:	Not Reported		
	Date:	06/1991		
13 ENE 1 - 2 Miles Higher	Site ID:	1863		
	Groundwater Flow:	Not Reported	AQUIFLOW	41857
	Shallowest Water Table Depth:	2.66		
	Deepest Water Table Depth:	4.40		
	Average Water Table Depth:	Not Reported		
	Date:	11/28/1995		
14 NNW 1 - 2 Miles Lower	Site ID:	5685010209		
	Groundwater Flow:	Not Reported	AQUIFLOW	61039
	Shallowest Water Table Depth:	Not Reported		
	Deepest Water Table Depth:	Not Reported		
	Average Water Table Depth:	8		
	Date:	04/05/1999		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database

EDR ID Number

15
SE
1 - 2 Miles
Higher

Site ID: 2244011310
Groundwater Flow: Not Reported
Shallowest Water Table Depth: 9
Deepest Water Table Depth: 10
Average Water Table Depth: Not Reported
Date: Not Reported

AQUIFLOW 60986

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KING County: 3

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KING COUNTY, WA

Number of sites tested: 106

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.334 pCi/L	99%	1%	0%
Living Area - 2nd Floor	0.800 pCi/L	100%	0%	0%
Basement	0.538 pCi/L	97%	3%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW[®] Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the national Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

Water Wells

Source: Department of Transportation
Telephone: 360-705-7444
Group A well location points in Washington State.

Kitsap County Water Wells in Washington

Source: Public Utility District No. 1 of Kitsap County
Telephone: 206-779-7656

RADON

Area Radon Information

Source: EPA
Telephone: 303-236-1525
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA
Telephone: 202-564-9370
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration



"Linking Technology with Tradition"

Sanborn® Map Report

Ship to: Patrick Romero
Parsons Brinckerhoff
999 3rd Avenue
Seattle, WA 98104

Order Date: 6/27/2002 **Completion Date:** 06/28/2002

Inquiry #: 806613.3S

P.O. #: na

Site Name: South Park Bridge

Address: 16th Ave South

City/State: Seattle, WA 98101

1065619CUR

206-382-5200

Cross Streets: South Orr St/Dallas Ave S

Based on client-supplied information, fire insurance maps for the following years were identified

1917 - 1 - map

1929 - 1 - map

1950 - 1 - map

1967 - 1 - map

Total Maps: 4

Limited Permission to Photocopy

Parsons Brinckerhoff (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

All maps provided pursuant to a Sanborn® Map Report are currently reproducible of fire insurance maps owned or licensed by Environmental Data Resources, Inc. NO WARRANTY, EXPRESSED OR IMPLIED IS MADE WHATSOEVER. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, WARRANTIES AS TO ACCURACY, VALIDITY, COMPLETENESS, SUITABILITY, CONDITION, QUALITY, MERCHANTABILITY, OR FITNESS FOR A PARTICULAR USE OR PURPOSE WITH RESPECT TO THE REPORT, THE MAPS, THE INFORMATION CONTAINED THEREIN, OR THE RESULTS OF A SEARCH OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. Environmental Data Resources, Inc. assumes no liability to any party for any loss or damage whether arising out of errors or omissions, negligence, accident or any other cause. In no event shall Environmental Data Resources, Inc., its affiliates or agents, be liable to anyone for special, incidental, consequential or exemplary damages.

Electronic Sanborn Map Images USER'S GUIDE

Thank you for your interest in electronic Sanborn Map images. The following are guidelines for accessing the images and for transferring them to your system. If you have any questions about the use of electronic Sanborn Map images, contact your EDR Account Executive at 1-800-352-0050.

Organization of Electronic Sanborn Image File

- First Page Sanborn Map Report, listing years of coverage
- Second Page Electronic Sanborn Map Images USER'S GUIDE
- Third Page Oldest Sanborn Map Image
- Last Page Most recent Sanborn Map Image

Navigating the Electronic Sanborn Image File

- Open file on screen.
- Identify TP (Target Property) on the most recent map.
- Find TP on older printed images.
- To view the image more clearly, zoom to 250%.
 - 200-250% is the approximate equivalent scale of hardcopy Sanborn Maps.
 - Viewing above 400% will tend to pixelate the display.
- Zooming in on an image:
 - Click on the % in the lower left hand corner and type in ____%.
 - Use the magnifying tool and drag a box around the TP area.

Printing a Sanborn Map from the Electronic File

- EDR recommends printing all images at 300 dpi (300 dpi prints faster than 600 dpi).
- To print only the TP area, cut and paste the area from Adobe Acrobat to your word processor.

For Adobe Acrobat Version 3

- Go to the Menu Bar.
- Highlight 'Tools'.
- Highlight 'Select Graphics'.
- Draw a box around the area of interest.
- Go to the Menu Bar.
- Highlight 'Edit'.
- Highlight 'Copy'.
- Go to a word processor such as Microsoft Word and paste. Print from the word processor.

For Adobe Acrobat Version 4

- Go to the Menu Bar.
- Press and hold the 'T' button.
- Choose the Graphics Select Tool.
- Draw a box around the area of interest.
- Go to the Menu Bar.
- Highlight 'Edit'.
- Highlight 'Copy'.
- Go to a word processor such as Microsoft Word and paste. Print from the word processor.




Text Select Tool (V)



Graphics Select Tool (V)


Important Information about Email Delivery of Electronic Sanborn Map Images

- Images are grouped into one file, up to 2MB.
- In cases where in excess of 6-7 map years are available, the file size typically exceeds 2MB. In these cases, you will receive multiple files, labeled as 1 of 3, 2 of 3, etc. including all available map years.
- Due to file size limitations, certain ISPs, including AOL, may occasionally delay or decline to deliver files. Please contact your ISP to identify their specific file size limitations.



Duwamish Waterway
500' wide

SEATTLE MAPS VOL. 12
1254
(338-362 VOL. 3)




The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1929 The Sanborn Library, LLC
 Year CJB
 EDR Research Associates

Reproduction in whole or in part of any map of The Sanborn Library, LLC may be prohibited without prior written permission from The Sanborn Library, LLC.



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1987 The Sanborn Library, LLC

CJB
EDR Research Associates

Reproduction in whole or in part of any map of The Sanborn Library, LLC may be prohibited without prior written permission from The Sanborn Library, LLC.

Appendix B

Hazardous Materials Site Screening Summary

This page intentionally blank

9. Hazardous Substances /Toxic Waste Impacts

Measure: Degree to which construction activities would disturb known hazardous waste sites or increase the risk of introducing Hazardous Substance contaminants into the environment.

Red = High probability of disturbing hazardous waste sites and possibly introducing Hazardous Substance contaminants into the environment.

YELLOW = Only a moderate probability of disturbing hazardous waste sites and introducing Hazardous Substance contaminants into the environment.

WHITE = No real probability of disturbing hazardous waste sites or introducing Hazardous Substance contaminants into the environment.

The findings for the South Park Bridge (SPB) 2 percent screening for Hazardous Substances in the subsurface at properties within the SPB project area from past and current activities are depicted on the attached GIS map. Properties with a high probability for having impacts to the subsurface media groundwater, soil, and/or sediment from Hazardous Substances are shown in red on the GIS map. Properties with a moderate potential for having impacts to the subsurface media from Hazardous Substances are shown in yellow on the GIS map. Properties with no real potential for having impacts to the subsurface media from Hazardous Substances are shown as white on the GIS map.

Properties selected by the screening process have a high probability of having environmental impacts to the subsurface media of soil, groundwater, and/or sediment. Subsurface media are interconnected and allow for contamination to be transmitted away from the source area. Subsurface environmental impacts can migrate through the soil and groundwater to an adjacent property and/or to sediments in the river. Environmental impacts to media within a project area can significantly burden any construction project with additional cost to mitigate these impacts.

Note: The 2 percent screening for Hazardous Substances constitutes only a preliminary screening of properties within the SPB project area. As such, this screening was based only on the publicly available information and the site visits described below. No subsurface sampling was conducted and no review of existing sample results was undertaken in connection with this screening. Also

Note: This report addresses only the potential for subsurface contamination of Hazardous Substances; it does not address the potential for Hazardous Substances in the building structures which might be demolished as a result of the various bridge alignment scenarios under consideration that encroach onto properties within the SBP project area. A Hazardous Substances inspection of these structures will be necessary in order to more fully assess the potential environmental impacts of the various bridge alignment scenarios, as well as, the

potential costs of any required Hazardous Substances abatement activities that would be associated with demolition.

South Park Bridge Project Area

The community of South Park is located on the western shore of the Duwamish River, approximately seven miles upstream from the mouth of the river, Elliott Bay. South Park forms the western boundary of the SPB project site. The eastern boundary of the SPB project is The Boeing Company's (Boeing's) Plant II facility (Plant II facility). The Boeing Plant II facility is a late 1930's to early 1940's aircraft manufacturing and assembly facility which occupies approximately 1.5 miles of the eastern shore of the Duwamish River.

The portion of the Duwamish River where the SPB project site is located is within the inter-tidal zone. The river level at this location fluctuates daily with tide cycle. At low tide, several drains and discharge pipes can be observed along both shores of the river.

The area in and around South Park became more developed and more industrial starting in the mid-1930's through the early-1950's. Rapid growth in the South Park area appears to parallel the development of Boeing's operations on the east side of the Duwamish River across from South Park. The types of operations at the properties within the SPB project area have varied over time. In several cases, the current operations at these properties do not reflect their past industrial activities.

Summary Screening of Activities

The findings for the South Park Bridge (SPB) 2 percent screening criteria for Hazardous Substances in the subsurface at properties within the SPB project area from past and current activities are based on the activities and information gathered summarized below. Properties within the SPB project area were screened initially by reviewing the following publicly available information: 1) the City of Seattle's Geographical Information System (GIS) database; 2) historical and current aerial photographs; and 3) federal and state agency records and database for Superfund sites and other cleanup actions. Properties were flagged for site visits based on the findings of the review of the public information. Site visits were conducted of the flagged properties.

Geographical Information System

The City of Seattle's GIS database was searched for all properties within the SPB project area that are listed as being Heavy Industrial and/or General Industrial. Those properties identified and/or listed as industrial were placed on the screening list for site visits.

Aerial Photographs

Seven sets of aerial photographs taken within the SPB project area from the 1930's, 1940's, 1950's, 1960's, 1970's, 1980's, and 1990's were obtained and analyzed to determine the types of past operations and activities that were conducted at a specific property over time. Properties that were found to have gas station operations, above ground storage tanks, industrial operations, ship repair yards, and/or auto junkyards were identified and added to the screening list for site visits.

Federal and State Agency Databases

The U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL) (Superfund Site list) was reviewed for properties within the SPB project area. Information listed by the Washington State Department of Ecology's (WADOE) on the WADOE's RCRA Cleanup Actions, the MTCA Site Cleanup Program, and the Hazardous Site Cleanup list were reviewed for properties located within the SPB project area. Any property that was listed on either the EPA's NPL or any of these WADOE lists were included on the screening list for site visits.

Site Visits

The initial screening of publicly available information flagged 46 properties within the SPB project area as having the potential/likelihood of environmental impacts to subsurface media as a result of past and/or present operations. Site visits were conducted of all 46 properties. Each site visit consisted only of observations of the subject property from public locations. As these properties are privately owned, there was no physical entry onto the subject properties. Twenty-three of the properties that were visited have been determined to have at least a moderate potential for environmental impacts to the subsurface from the past and/or current release of Hazardous Substances from past and/or current operations. Fifteen of these 23 properties were determined to have a high potential for environmental impacts to the subsurface from the past and/or current release of Hazardous Substances from past and/or current operations.

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 1

Date:

4/2002

Site Assessment Conducted by:

J. S. WILBUR

Property Address:

7700 14th AVE. S.

SEATTLE, WA

(206) 441-1111

Current Business Operation:

FORMER GAS MANUFACTURE

Current Business Name:

AIR CO.

Photograph: yes ☒ no ☐

Direction of Photograph: ☐ North ☒ South ☐ East ☒ West

Aerial Photographs:

☒ 1940s ☐ 1950s ☐ 1960s ☐ 1970s ☐ 1980s ☐ 1990s

AIR CO OPERATIONS IN 1986

AERIAL PHOTOGRAPH ---

LARGE SETTING TANKS ON SITE

Polk Directory

1944 AIR CO

1954

1964

1974

1984

1994

UST Information:

Surface fueling system

yes ☐ no ☒

Visible Vent Pipes

yes ☒ no ☐

Monitoring Wells

yes ☒ no ☐

Number of wells

SEVEN

Hazardous Material Storage Area yes ☒ no ☐

Federal Listings

NONE

State Listings

WIDE HAZ. WASTE SITE

Local/Regional Listings

NONE


Sanborn Maps:

☒ 19 AIR CO

☐ 19

☐ 19

☐ 19



SURFACE CLEANING
BEING CONSIDERED
- PROGRAM 3.7E

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 2

Date: 4/2002
 Site Assessment Conducted by: J.S. WILCOX
 Property Address: 7733 16th AVE. S.
SEATTLE, WA
(77777)

Current Business Operation: PARKING LOT - THE BOEING COMPANY
 Current Business Name: PARKING LOT

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☒ East ☐ West

Aerial Photographs: FOUNDER LARSEN
☐ 1940s SEATTLE POND FOR AIR CO
☐ 1950s OPERATIONS
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s PARKING LOT


Polk Directory
☒ 1944 AIR CO
☒ 1954
☒ 1964
☒ 1974
☒ 1984
☒ 1994

Parcel ID Number: N/A
 Tax ID Number: _____
 Seattle GIS Use Code: _____
 Sanborn Maps: _____

UST Information:
 Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒
 Federal Listings NONE
 State Listings ✓
 Local/Regional Listings ✓
NOTE - SEATTLE POND EXCAVATED IN 1960'S

Sanborn Maps:
☐ 19____
☐ 19____
☐ 19____
☐ 19____



4/2002

Site Assessment Conducted by:

7745 16th AVE. S.

SEATTLE WA
(Tukwila)

PARKING LOT

PARKING LOT

yes ☐ no ☒

☐ North

Polk Directory

W

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

Surface fueling system

yes ☐

yes ☐

yes ☐

non

work

W3NR

1951

19

10

10

No Photograph

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 4

Date: 4/2002
 Site Assessment Conducted by: J.S. WILBURN

Property Address: 7747 14th AVE. S.
SEATTLE, WA
(TUKWILA)

Current Business Operation: PARKING LOT - THE BOEING COMPANY
 Current Business Name: PARKING LOT - LATE 1990's

Photograph: yes ☐ no ☒
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

Parcel ID Number:	<u>NA</u>	<input checked="" type="checkbox"/> 1940s	<u>Small structure 1947</u>	<input type="checkbox"/> 1944	<u>Boeing</u>
Tax ID Number:		<input checked="" type="checkbox"/> 1950s		<input type="checkbox"/> 1954	
Seattle GIS Use Code:		<input checked="" type="checkbox"/> 1960s		<input type="checkbox"/> 1964	
Sanborn Maps:		<input type="checkbox"/> 1970s	<u>BANK - FIRST INDUSTRIAL</u>	<input type="checkbox"/> 1974	
		<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984	
		<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994	

Polk Directory

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings None
 State Listings None
 Local/Regional Listings None

Sanborn Maps:

☐ 19 NO ISSUES IDENTIFIED
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 5

NOTE: 1920s - Built on Stoneage Facility
to Stone curb

Date: _____
 Site Assessment Conducted by: J.S. Wilgus
 Property Address: BOEING PLANT 2
N. CAMPBELL AVE

Current Business Operation: AIRCRAFT MANUFACTURING
 Current Business Name: THE BOEING COMPANY

Photograph: yes ☒ no ☐
 Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:

Parcel ID Number:	<u>0005</u>	<u>NOTED</u>	<u>1944</u>	<input checked="" type="checkbox"/> 1944	<u>NOT LISTED</u>
Tax ID Number:				<input type="checkbox"/> 1954	
Seattle GIS Use Code:	<u>GI</u>			<input type="checkbox"/> 1964	
Sanborn Maps:				<input type="checkbox"/> 1974	
				<input type="checkbox"/> 1984	
				<input type="checkbox"/> 1994	<input checked="" type="checkbox"/>

UST Information:


Surface fueling system yes ☐ no ☒ OIL HOUSE
 Visible Vent Pipes yes ☐ no ☒ BOILER HOUSE
 Monitoring Wells yes ☐ no ☒
 Number of wells 6

Hazardous Material Storage Area

Federal Listings yes ☒ no ☐
RCA / SUPERFUND
 State Listings RCA
 Local/Regional Listings

Sanborn Maps:

<input type="checkbox"/> 1927	<u>SPAWNS ON COLL. - BUILT OIL FACILITY</u>
<input type="checkbox"/> 19	
<input type="checkbox"/> 19	
<input type="checkbox"/> 19	



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 6

Date: 4/2002
 Site Assessment Conducted by: J.S. WILSON
 Property Address: THE BOEING COMPANY PLANT 2
OFFICE BUILDING -
SOUTH SIDE OF 16th AVE. S.

Current Business Operation: OFFICE BUILDING / AIRCRAFT MANUFACTURING
 Current Business Name: THE BOEING COMPANY


Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☒ South ☐ East ☐ West

	Aerial Photographs:	Polk Directory
Parcel ID Number:	<u>N/A</u>	<u>NOT LISTED</u>
Tax ID Number:		
Seattle GIS Use Code:		
Sanborn Maps:		
	<input checked="" type="checkbox"/> 1940s	<input type="checkbox"/> 1944
	<input type="checkbox"/> 1950s	<input type="checkbox"/> 1954
	<input type="checkbox"/> 1960s	<input type="checkbox"/> 1964
	<input type="checkbox"/> 1970s	<input type="checkbox"/> 1974
	<input type="checkbox"/> 1980s	<input type="checkbox"/> 1984
	<input type="checkbox"/> 1990s	<input type="checkbox"/> 1994

UST Information:
 Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☒ no ☐
 Number of wells SEVEN

Hazardous Material Storage Area yes ☒ no ☐
 Federal Listings RCRA
 State Listings RCRA, WST
 Local/Regional Listings

Sanborn Maps:
☐ 1927 FROM LAND -
☐ 19
☐ 19
☐ 19



15:1920-1938 A STRAW PLAT SHOP WAS LOCATED
NEAR THE WATER PLANT 2 FOOT PLANT ---

4/2002
F.S. WILK

T.S. WILBURN

Current Business Operation: AIRCRAFT MAINTENANCE

Current Business Name: THE BOKWU COMPANY

Photograph: yes ☒ no ☐

☐ West

Polk Directory 325.446

1944

1954 □

1964

1974

Surface fueling system	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>
Visible Vent Pipes	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>
Monitoring Wells	yes <input checked="" type="checkbox"/>	no <input type="checkbox"/>
Number of wells	SEVEN	

Hazardous Material Storage Area yes ☒ no ☐
 Federal Listings RCRA, CERCLA, STOS, ILINK, NPL
 State Listings UST, CUST

<input type="checkbox"/>	19__
<input type="checkbox"/>	19__
<input type="checkbox"/>	19__
<input type="checkbox"/>	19__



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site A

Date: 4/2002
 Site Assessment Conducted by: J.S. WILSON
 Property Address: EAST STONE LANE
DUNN, WA WATERWAY
SKATTE, WA - PLANT 2
 Current Business Operation: STONE LIME / PLANT 2 N. COMPANY
 Current Business Name: _____
 Photograph: yes ☒ no ☐
 Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:

<input checked="" type="checkbox"/> 1940s	— WWII	MOTOR POOL AREA	US ARMY	<input checked="" type="checkbox"/> 1944	NOT LISTED
<input type="checkbox"/> 1950s	1950s	— BOWEN DEVELOPS		<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		ANALYSIS MANUFACTURING		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s				<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s				<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s				<input type="checkbox"/> 1994	

Polk Directory

<input checked="" type="checkbox"/> 1940s	— WWII	MOTOR POOL AREA	US ARMY	<input checked="" type="checkbox"/> 1944	NOT LISTED
<input type="checkbox"/> 1950s	1950s	— BOWEN DEVELOPS		<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		ANALYSIS MANUFACTURING		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s				<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s				<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s				<input type="checkbox"/> 1994	

Parcel ID Number: N/A
 Tax ID Number: _____
 Seattle GIS Use Code: N/A
 Sanborn Maps: _____


UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒
 Federal Listings NPL SITE (SUPERFUND)
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet
South Park Bridge Project
Site B

Date: 4/2002
 Site Assessment Conducted by: T.S. WILBUR

Property Address: NA
 Current Business Operation: WESTERN SHORELINE LOW
 Current Business Name: _____

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☒ East ☐ West

Aerial Photographs:

<input type="checkbox"/> 1940s	<u>SHORELINE</u>	<input type="checkbox"/> 1944	<u>NOT LISTED</u>
<input type="checkbox"/> 1950s		<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s		<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994	

Parcel ID Number: NA
 Tax ID Number: NA
 Seattle GIS Use Code: NA
 Sanborn Maps: _____

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NPL SITE / POWER DYNAMISM WAREHOUSE
 State Listings SENIORMENT LISTING
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 8

Date: 4/2002
 Site Assessment Conducted by: J. S. WILSON

Property Address: SOUTH PARK MARINA
1289 S. PACE ST.
SEATTLE, WA

Current Business Operation: BOAT REPAIR YARD
 Current Business Name: -- SOUTH PARK MARINA --

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☒ South ☐ East ☐ West

Aerial Photographs:

<input type="checkbox"/> 1940s	<u>STRUCTURE -- 1947</u>	<input type="checkbox"/> 1944	<u>NOT LISTED</u>
<input type="checkbox"/> 1950s	<u>BOAT YARD</u>	<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s	<u>BOAT YARD -- HARVEST SMITH</u>	<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s	<u>GRAND SERVICE</u>	<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s	<u>-- ADRIAN T. SURGE</u>	<input type="checkbox"/> 1994	

Polk Directory

Parcel ID Number: NA
 Tax ID Number: _____
 Seattle GIS Use Code: _____
 Sanborn Maps: _____

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒
 Federal Listings None
 State Listings None
 Local/Regional Listings None

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____
☐ 19____



POOR HOUSE KEEPING
 SHOWN DRAWING --
 CENTER of MARINA --
 CHIMNEY STAIRS
 IN CORNERS

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 9

Date: 4/2002
 Site Assessment Conducted by: J.S. WILBUR
 Property Address: 1400 SOUTH THISTLE ST.
SEATTLE, WA

Current Business Operation: BOAT REPAIR YARD/WAREHOUSE
 Current Business Name: NOT KNOWN

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

<input checked="" type="checkbox"/> 1940s	CINQUE BOUL STRUCTURE LOCATED	<input type="checkbox"/> 1944	NOT LISTED
<input type="checkbox"/> 1950s	IN 1947 AERIAL PHOTOGRAPHY	<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s	BUILDING USED TO STORE BOATS	<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s	J. MENS	<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994	

Polk Directory

<input type="checkbox"/> 1944	NOT LISTED
<input type="checkbox"/> 1954	
<input type="checkbox"/> 1964	
<input type="checkbox"/> 1974	
<input type="checkbox"/> 1984	
<input type="checkbox"/> 1994	

Parcel ID Number: 0840
 Tax ID Number:
 Seattle GIS Use Code: R/B
 Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells

Hazardous Material Storage Area

yes ☐ no ☒
 Federal Listings NO
 State Listings NO
 Local/Regional Listings NO

Sanborn Maps:

☐ 19
☐ 19
☐ 19
☐ 19



-- BOAT SHOP

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 10

Date: 4/2002
 Site Assessment Conducted by: J.S. WILBIE

Property Address: 8450 14th AVE. S.
SEATTLE, WA

Current Business Operation: BAR J GRILL
 Current Business Name: COUNTRY LUNC. BAR J GRILL

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

<input checked="" type="checkbox"/> 1940s	<u>STRUCTURE PRESENT IN 1936 AERIAL</u>	<input type="checkbox"/> 1944	<u>HARDWARE</u>
<input type="checkbox"/> 1950s	<u>PHOTOMAN</u>	<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s		<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994	

Parcel ID Number: 1045
 Tax ID Number: _____
 Seattle GIS Use Code: RB
 Sanborn Maps: _____

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____


Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

<input type="checkbox"/> 19	_____
<input type="checkbox"/> 19	_____
<input type="checkbox"/> 19	_____
<input type="checkbox"/> 19	_____

NOTE: NORTH PORTION OF PROPERTY IS USED AS
 BOAT YARD. OPERATIONS AS A BOAT YARD
 FROM 1970 - PRESENT (SEE HOOK REFERRING)
 SURFACE DRAINAGE.



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 11

Date: 4/2002

Site Assessment Conducted by: TS WILBUR

Property Address: 1401 S. THURGOOD ST.

SEATTLE, WA

Current Business Operation: HOUSE w/ JUNK YARD

Current Business Name: _____

Photograph: yes ☒ no ☐

Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:

<input checked="" type="checkbox"/> 1940s	HOUSE IN 1934 AERIAL PHOTOGRAPH	<input type="checkbox"/> 1944	<u>RESIDENCE</u>
<input type="checkbox"/> 1950s		<input type="checkbox"/> 1954	
<input type="checkbox"/> 1960s		<input type="checkbox"/> 1964	
<input type="checkbox"/> 1970s		<input type="checkbox"/> 1974	
<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984	
<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994	

Polk Directory

UST Information:

Surface fueling system yes ☐ no ☒

Visible Vent Pipes yes ☐ no ☒

Monitoring Wells yes ☐ no ☒

Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE

State Listings NONE

Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____

☐ 19 _____

☐ 19 _____

☐ 19 _____



JUNK YARD
SUBSIDIARY
HOUSE

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 12

Date: 4/2002

Site Assessment Conducted by: J.S. WILBUR

Property Address: 8510 14th Ave. S.
SEATTLE, WA
1411 SOUTH THISTLE ST
SEATTLE, WA

Current Business Operation: BOAT REPAIR YARD

Current Business Name: UNKNOWN

Photograph: yes ☒ no ☐

Direction of Photograph: ☐ North ☐ South ☒ East ☐ West

Aerial Photographs:

Year	Photograph	Polk Directory
<input checked="" type="checkbox"/> 1940s	<u>STRUCTURE PRESENT IN 1934</u>	<input checked="" type="checkbox"/> 1944 <u>VACANT</u>
<input type="checkbox"/> 1950s	<u>Abolished</u>	<input type="checkbox"/> 1954
<input type="checkbox"/> 1960s		<input type="checkbox"/> 1964
<input type="checkbox"/> 1970s		<input checked="" type="checkbox"/> 1974 <u>VACANT</u>
<input type="checkbox"/> 1980s		<input type="checkbox"/> 1984
<input type="checkbox"/> 1990s		<input type="checkbox"/> 1994

Parcel ID Number: 8825 N/A

Tax ID Number: 2

Seattle GIS Use Code: 2

Sanborn Maps:

UST Information:

Surface fueling system: yes ☐ no ☒

Visible Vent Pipes: yes ☐ no ☒

Monitoring Wells: yes ☐ no ☒

Number of wells: _____

Hazardous Material Storage Area: yes ☐ no ☒

Federal Listings: NONE

State Listings: NONE

Local/Regional Listings: NONE

Sanborn Maps:

☐ 19 _____

☐ 19 _____

☐ 19 _____

☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 13

Date: 4/2002

Site Assessment Conducted by: J.S. WILCOX

Property Address: 8510 14th AVE. S.

SEATTLE, WA

Current Business Operation: TIRE/AUTO REPAIR

Current Business Name: TIRE FACTORY

Photograph: yes ☒ no ☐

Direction of Photograph: ☐ North ☒ South ☐ East ☐ West

Aerial Photographs:

☐ 1940s STRIPES PRESENT IN 1947
☐ 1950s
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory

☐ 1944 NOT LISTED
☐ 1954 VACANT
☐ 1964 SOUTH PARK AUTO PARTS
☐ 1974 "
☐ 1984 Eds Plastic 2nd floor
☐ 1994 NOT LISTED

Parcel ID Number: NA

Tax ID Number: I

Seattle GIS Use Code: I

Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____
☐ 19____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 14

Date: 4/2002
 Site Assessment Conducted by: J.S. Wilson
 Property Address: 8457 14th Ave, S.
SEATTLE, WA

Current Business Operation: RESTAURANT
 Current Business Name: TERIYAKI FASH FOOD TRUCK

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☒ South ☐ East ☐ West

Aerial Photographs:

☐ 1940s
☐ 1950s
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Parcel ID Number: N/A
 Tax ID Number: _____
 Seattle GIS Use Code: _____
 Sanborn Maps: _____

Polk Directory
☐ 1944 NOT LISTED
☐ 1954 NOT LISTED
☐ 1964 NOT LISTED
☐ 1974 NOT LISTED
☐ 1984 NOT LISTED
☐ 1994 NOT LISTED

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area

yes ☐ no ☒
 Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 15

Date: 4/2002

Site Assessment Conducted by: JTS WILSON

Property Address: 8506 14th AVE
SEATTLE, WA

Current Business Operation:

Current Business Name:

COMMUNION/RESTAURANT/DAY CLEANERS
SEC 0800R

Photograph: yes ☒ no ☐

Direction of Photograph: ☐ North ☐ South ☐ East ☐ West

Aerial Photographs:

- ☒ 1940s STANDARD PRESENT IN 1934
☒ 1950s AERIAL PHOTOGRAPH
☒ 1960s
☒ 1970s
☒ 1980s
☒ 1990s

Parcel ID Number: 8688

Tax ID Number: NC

Seattle GIS Use Code:

Sanborn Maps:

Polk Directory

- ☒ 1944 BEEL PARKER, BARBER
☒ 1954 KLEEN-RITE CLEANERS
☒ 1964 B-TWEEN DAY DAY LAUNDRY
☒ 1974 VACANT
☒ 1984 DRHOL. SHOP.
☒ 1994 WILKENS - E10R

UST Information:


- Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

- Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

- ☐ 19 _____
☐ 19 _____
☐ 19 _____



- 1) PATTAYA THAI RESTAURANT
 - 2) DAY CLEANERS - DUMPING IN STORM SEWER.
 - 3) DOUXE
- NOTE: POTENTIAL ISSUES-

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 16

Date: 4/2002
 Site Assessment Conducted by: IS. WILBUR
 Property Address: 8SD7 14th AVE. S.
SEATTLE, WA

Current Business Operation: MARKET
 Current Business Name: DISCOUNT MARKET

Photograph: yes ☐ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☐ West

Aerial Photographs:

☒ 1940s STRUCTURE IN 1947 AERIAL
☒ 1950s PHOTOGRAPH
☒ 1960s
☒ 1970s
☒ 1980s
☒ 1990s

Polk Directory

☐ 1944
☒ 1954 SAFE WAY STORE
☒ 1964 SA VACANT
☒ 1974 NATIONAL AUTO PARTS
☒ 1984 JTS ENTERPRISES
☒ 1994 VACANT

Parcel ID Number: 75SD
 Tax ID Number: _____
 Seattle GIS Use Code: NC
 Sanborn Maps: _____

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area

yes ☐ no ☒
 Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 17

Date:

Site Assessment Conducted by:

Property Address:

Current Business Operation:

Current Business Name:

Photograph:

Direction of Photograph:

Aerial Photographs:

Parcel ID Number:

Tax ID Number:

Seattle GIS Use Code:

Sanborn Maps:

UST Information:

Surface fueling system

Visible Vent Pipes

Monitoring Wells

Number of wells

Hazardous Material Storage Area

Federal Listings

State Listings

Local/Regional Listings

Sanborn Maps:

19

19

19

4/2002

J.S. WILSON

8514 14 AVE S.

SEATTLE, WA

BUENA VISTA MAULE

BUENA VISTA MAULE

yes ☒ no ☐

☐ North

☐ South

☐ East

☐ West

Polk Directory

☐ 1944 VARIETY STORE

☐ 1954 RETAIL

☐ 1964 GUNNERS

☐ 1974 VACANT

☐ 1983 CHUCK BERGLAND

☐ 1994 INSULATION

☐ 1940s GUNNERS

☐ 1950s

☐ 1960s

☐ 1970s

☐ 1980s

☐ 1990s

no ☒

no ☒

no ☒

no ☒

NONE

NONE

NONE



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 18

Date: 4/2002
 Site Assessment Conducted by: J.S. WILLIAMS

Property Address: 8524 14th AVE. S
SEATTLE, WA

Current Business Operation: SERVICE STATION
 Current Business Name: HERBS REPAIR

Photograph: yes ☐ no ☐
 Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:

Parcel ID Number: NA
 Tax ID Number: NA
 Seattle GIS Use Code: NA
 Sanborn Maps: NA

Polk Directory

☐ 1940s STRUCTURE (GAS STATION) SEEN IN
☐ 1950s 1934 AERIAL PHOTOGRAPH
☐ 1960s 1934 AERIAL PHOTOGRAPH
☐ 1970s 1934 AERIAL PHOTOGRAPH
☐ 1980s 1934 AERIAL PHOTOGRAPH
☐ 1990s 1934 AERIAL PHOTOGRAPH

UST Information:


Surface fueling system: yes ☒ no ☐
 Visible Vent Pipes: yes ☒ no ☐
 Monitoring Wells: yes ☐ no ☒
 Number of wells: 1

Hazardous Material Storage Area: yes ☐ no ☒

Federal Listings: None
 State Listings: WIDEN SPILL, ID 515521
 Local/Regional Listings: WIDEN SPILL, ID 515521

Sanborn Maps:

☐ 19 19
☐ 19 19
☐ 19 19
☐ 19 19



1934/1937
 SOUTH PARK
 TEXAS

Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 19

Date: 4/2002
 Site Assessment Conducted by: T.S. WILSON
 Property Address: 851 S 14th AVE. S.
SEATTLE, WA

Current Business Operation: RESTAURANT
 Current Business Name: MUY MACHO

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☐ 1940s ☐ 1950s ☐ 1960s ☐ 1970s ☐ 1980s ☐ 1990s

Parcel ID Number: 7567
 Tax ID Number: _____
 Seattle GIS Use Code: NC
 Sanborn Maps: _____

Polk Directory

☐ 1944 CHEAT DAVE CAFE
☐ 1954 CHEAT DAVE CAFE
☐ 1964 1
☐ 1974 1
☐ 1984 1
☐ 1994 _____

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area

yes ☐ no ☒
 Federal Listings NOA/IC
 State Listings NOA/IC
 Local/Regional Listings NOA/IC

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 20

Date: 4/2002
 Site Assessment Conducted by: J.S. WILSON
 Property Address: 8517 14th Ave. S.
SEATTLE, WA

Current Business Operation: RESTAURANT
 Current Business Name: TALISCO MEXICAN

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☐ 1940s CURRENT STRUCTURE IN 1934
☐ 1950s Aerial PHOTOGRAPH
☐ 1960s _____
☐ 1970s _____
☐ 1980s _____
☐ 1990s _____

Polk Directory

☒ 1944 NOT LISTED
☒ 1954 WALICA TRUCK
☒ 1964 N.W. APP. 744W
☒ 1974 NOT LISTED
☒ 1984 ALORENE
☐ 1994 TALISCO MEXICAN

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 21

Date: 4/2002
 Site Assessment Conducted by: F.S. WING

Property Address: 8527 1st AVE S.
SEATTLE, WA

Current Business Operation: APARTMENT BUILDING
 Current Business Name: NOT KNOWN

Photograph: yes ☒ no ☐
 Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:
☒ 1940s STRUCTURE PRESENT IN 1934
☐ 1950s AIR PHOTO GRAPHS
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory
☐ 1944 NOT LISTED
☐ 1954 (RESIDENT?)
☐ 1964
☐ 1974
☐ 1984
☐ 1994 ✓

Parcel ID Number: NA
 Tax ID Number: NA
 Seattle GIS Use Code:
 Sanborn Maps:

UST Information:
 Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒
 Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:
☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 22

Date: 4/2002
 Site Assessment Conducted by: J.S. WILBUR

Property Address: 8601 14th AVE. S.
SEATTLE, WA

Current Business Operation: MARKET /
 Current Business Name: EL MOLINO ROAD

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☒ 1940s ☐ 1950s ☐ 1960s ☐ 1970s ☐ 1980s ☐ 1990s

Polk Directory

☐ 1940s ☐ 1954 ☐ 1964 ☐ 1974 ☐ 1983 ☐ 1994

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 23

Date: 4/2002
 Site Assessment Conducted by: IS WILBUR
 Property Address: BLD 3 14th AVE S.
SEATTLE, WA

Current Business Operation: MARKET
 Current Business Name: MEXI-MART

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☐ 1940s PRESENT IN 1934 AERIAL PHOTOGRAPH
☐ 1950s
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory

☐ 1944 ALL OLD. PRSP
☐ 1954 SHOE REPAIR
☐ 1964 NOT LISTED
☐ 1974 NOT LISTED
☐ 1983 NOT LISTED
☐ 1994 JERICHO INN MISSION

Parcel ID Number: NA

Tax ID Number: NA

Seattle GIS Use Code: NA

Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 24

Date: 4/2002
 Site Assessment Conducted by: J.S. Wilson

Property Address: 8611 14th Ave, S.
SEATTLE, WA

Current Business Operation: RETAIL - SOUTH PARK HALL
 Current Business Name: 3 RETAILS / EL VARGA MARIANO / MUSICA Y VIDEO / VACANT

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☐ 1940s PRESENT IN 1934 AERIAL PHOTOGRAPH
☐ 1950s _____
☐ 1960s _____
☐ 1970s _____
☐ 1980s _____
☐ 1990s _____

Polk Directory

☐ 1944 BAKER
☐ 1954 SOUTH PARK BAKER
☐ 1964 SOUTH PARK BAKER
☐ 1974 VACANT
☐ 1983 PONY EXPRESS
☐ 1994 VACANT

Parcel ID Number: NA
 Tax ID Number: _____
 Seattle GIS Use Code: NA
 Sanborn Maps: _____

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 25

Date:

4/2002

Site Assessment Conducted by:

J.S. WILBUR

8600 14th AVE. S.

Current Business Operation:

RESTAURANT

Property Address:

8600 14th AVE. S.

Current Business Name:

NAPOLI PIZZERIA

SEATTLE, WA

Photograph: yes ☒ no ☐

Direction of Photograph: ☒ North ☐ South ☐ East ☐ West

Aerial Photographs:

☐ 1940s ☐ 1950s ☐ 1960s ☐ 1970s ☐ 1980s ☐ 1990s

PRESENT IN 1941 AERIAL PHOTOGRAPH

Polk Directory

☐ 1944 ☐ 1954 ☐ 1964 ☐ 1974 ☐ 1984 ☐ 1994

SOUTH PARK PHARMACY
CAPRI PIZZERIA
NAPOLI PIZZERIA

Parcel ID Number:

8654

Tax ID Number:

NV

Seattle GIS Use Code:

Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
Visible Vent Pipes yes ☐ no ☒
Monitoring Wells yes ☐ no ☒
Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
State Listings NONE
Local/Regional Listings NONE

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____
☐ 19____



Initial Environmental Site Assessment Data Sheet
South Park Bridge Project
Site 26

Date: 4/2002
Site Assessment Conducted by: J.S. WUBER

Property Address: 8413 14th AVE. S
SEATTLE, WA

Current Business Operation: VACANT BUILDING
Current Business Name: VACANT

Photograph: yes ☒ no ☐
Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☒ 1940s STRUTTING IN 1936 AERIAL
☐ 1950s PHOTOGRAPH
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory

☐ 1944 VARIETY STORE
☐ 1954 SOUTH PARK BILLIARDS
☐ 1964 V
☐ 1974 VACANT
☐ 1983 POW EXHIBITS MAIL BOX
☐ 1994 V

Parcel ID Number: NA
Tax ID Number: NA
Seattle GIS Use Code:
Sanborn Maps:


UST Information:

Surface fueling system yes ☐ no ☒
Visible Vent Pipes yes ☐ no ☒
Monitoring Wells yes ☐ no ☒
Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒
Federal Listings NONE
State Listings NONE
Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 27

Date: 4/2002
 Site Assessment Conducted by: J.S. WILBUR

Property Address: 8617 14th AVE. S.
SEATTLE, WA

Current Business Operation: KELLY'S TAVERN
 Current Business Name: KELLY'S TAVERN

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

☐ 1940s CURRENT STRUCTURE PHOTOGRAPH
☐ 1950s IN 1936 AERIAL PHOTOGRAPH
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory

☒ 1944 BEECE PARKER
☒ 1954 KELLY'S TAVERN
☒ 1964
☒ 1974
☒ 1984
☒ 1994

Parcel ID Number: 7841

Tax ID Number: _____

Seattle GIS Use Code: NL

Sanborn Maps: _____

UST Information:

Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE

State Listings NONE

Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 28

Date: 4/10/02
 Site Assessment Conducted by: J.S. WILSON
 Property Address: 8616 N 4th Ave. S
SEATTLE, WA

Current Business Operation: APARTMENT HOUSE
 Current Business Name: NONE

Photograph: yes ☐ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☐ West

Aerial Photographs:

Parcel ID Number: 8684
 Tax ID Number: _____
 Seattle GIS Use Code: NL
 Sanborn Maps: _____

Polk Directory

	1944	1954	1964	1974	1984	1994
1940s	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1950s	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1960s	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1970s	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1980s	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1990s	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

STANLEY PRESENT IN 1936
ARMED PHOTOGRAPH
DOCTOR OFFICE
RESIDENCE
SEATTLE PUBLIC
WOLFE
APARTMENTS
APARTMENTS

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells _____

Hazardous Material Storage Area yes ☐ no ☒

Federal Listings NONE
 State Listings NONE
 Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 29

Date: 4/2002
 Site Assessment Conducted by: E.S. Wilson
 Property Address: 8421 14th Ave. S.
SFAIR

Current Business Operation: SWEEP SHOP / SEWING
 Current Business Name: BABAS SEWING

Photograph: yes ☒ no ☐
 Direction of Photograph: ☐ North ☐ South ☐ East ☒ West

Aerial Photographs:

- ☒ 1940s STRUCTURE IN IN 1930s AREA
☐ 1950s PHOTOGRAPH - GAS STATION
☐ 1960s
☐ 1970s
☐ 1980s
☐ 1990s

Polk Directory

- ☐ 1944 FRANK GAS STATION
☐ 1954 AUTOMOTIVE REPAIR
☐ 1964 BUS FRANK'S WHEEL
☐ 1974 SANITARIUM FRANK JONES
☐ 1983 +
☐ 1994 ALL-STATE TRANSIT

Parcel ID Number: 8110
 Tax ID Number: NL
 Seattle GIS Use Code:
 Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
 Visible Vent Pipes yes ☐ no ☒
 Monitoring Wells yes ☐ no ☒
 Number of wells

Hazardous Material Storage Area

yes ☐ no ☒
 Federal Listings None
 State Listings LCR SITE
 Local/Regional Listings None

Sanborn Maps:

☐ 19____
☐ 19____
☐ 19____
☐ 19____



Initial Environmental Site Assessment Data Sheet

South Park Bridge Project

Site 30

CHEMICAL TANK STORAGE IN BACK -
POSSIBILITY IN POOR CONDITION -

Date: 4/1/00
Site Assessment Conducted by: J.S. WILSON

FORMER SERVICE STATION - 1940s - 1960s
FORMER DAY CUPBOARD 1960 - 1990s

Current Business Operation:
Current Business Name:

Property Address: 8620 14th AVE. S.
SEATTLE, WA

NONE

Photograph: yes ☒ no ☐
Direction of Photograph: ☐ North ☐ South ☒ East ☐ West

Aerial Photographs:

☒ 1940s STATIONING IN 1947 Aerial PHOTOGRAPH ☐ 1944 NOT LISTED
☐ 1950s ☐ 1954 NAT. CHEVROLET STATION
☐ 1960s ☐ 1964 HY-TONE CUPBOARD
☐ 1970s ☐ 1974 SOUTH PARK CUPBOARD
☐ 1980s ☐ 1983 BELVISTA DRAPERS, WA
☐ 1990s ☐ 1994 NOT VERIFIED

Polk Directory

☐ 1944 NOT LISTED
☐ 1954 NAT. CHEVROLET STATION
☐ 1964 HY-TONE CUPBOARD
☐ 1974 SOUTH PARK CUPBOARD
☐ 1983 BELVISTA DRAPERS, WA
☐ 1994 NOT VERIFIED

Parcel ID Number: 8683

Tax ID Number: NL

Seattle GIS Use Code: NL

Sanborn Maps:

UST Information:


Surface fueling system yes ☐ no ☒
Visible Vent Pipes yes ☒ no ☐
Monitoring Wells yes ☐ no ☒
Number of wells _____

Hazardous Material Storage Area yes ☐ no ☐

Federal Listings NONE
State Listings NONE
Local/Regional Listings NONE

Sanborn Maps:

☐ 19 _____
☐ 19 _____
☐ 19 _____
☐ 19 _____



Map Label	Address/location	Business Name	NPL	RCRA	UST	LUST	FIR	Substantially Contaminated	Reasonably Predictable	PSI Recommended
1	7700 14th Avenue South	Former Air CO property							X	
2	7733 16th Avenue South	The Boeing Company Parking Lot								
3	7745 16th Avenue South	First InterBank of Kirkland/Vacant Lot						X		
4	7747 16th Avenue South	Vacant Lot						X		X
5	Boeing's Plant II North Campus Area	The Boeing Company North Side 16th Avenue		X				X		
6	Boeing's Plant II Bdg 2-41 Area	The Boeing Company South Side 16th Avenue		X				X		(X)
7	Boeing's Plant II Bdg 2-41 Area	The Boeing Company South Side 16th Avenue	X					X		(X)
A	East Sediment Area Duwamish Waterway	NA	X					X		
B	West Sediment Area Duwamish Waterway	NA						X		
8	1289 South Rose Street	South Park Marine								X
9	1400 South Thistle Street	Rem Company								X
10	8456 14th Avenue South	County Line Bar and Grill								X
11	1401 South Thistle Street	House					X			
12	1411 South Thistle Street	Marine								
13	8510 14th Avenue South	Tire Factory								
14	8457 14th Avenue South	Teriyaki Fast Food to Go								
15	1257 South Sullivan Street	Pattaya Thai Restaurant								
15	8508 14th Avenue South	Dry Cleaners -name?-							X	
15	8510 14th Avenue South	DolEX								
16	8507 14th Avenue South	Discount market								(X)
17	8514 14th Avenue South	Buena Vista Travel					X		X	(X)
18	8520 14th Avenue South	Salon Expo					X		X	(X)
18	8524 14th Avenue South	Herbs Repair/ Taxi Meters					X		X	
18	8524 14th Avenue South	Coffee Stand								
19	8515 14th Avenue South	Muy Macho								
20	8517 14th Avenue South	Jalisco Mexican Restaurant								
21	8527 14th Avenue South	Apartment Building								
22	8601 14th Avenue South	El Molino Rolo								
23	8601 14th Avenue South	Mex-Mart								
24	8611 14th Avenue South	El Vargre Marind								
24	8611 14th Avenue South	Musica & Video								
24	8611 14th Avenue South	South Park Hall								X
25	8600 14th Avenue South	Napoli Pizzeria								
26	8613 14th Avenue South	Vacant Brick Building								
27	8617 14th Avenue South	Kelly's Tavern								
28	8616 14th Avenue South	House					X		X	X
29	8621 14th Avenue South	Babbas Sewing					X		X	X
30	8620 14th Avenue South	Former Gas Station & Dry Cleaner								
31	8701 14th Avenue South	Sea Mar Community Health office								X
32	8700 14th Avenue South	R.L Cook Sales & Supply Warehouse					X		X	(X)
33	8709 14th Avenue South	Juan Colorado Restaurant					X		X	(X)
35	8721 14th Avenue South	Parking Lot								
35	8721 14th Avenue South	A.D. Swayne Company								
36	8722 14th Avenue South	Sea Mar Community Health Clinic								

Map Label	Address/location	Business Name	NPL	RCRA	UST	LUST	FIR	Substantially Contaminated	Reasonable Potential	Recommended PSL
37	No longer in project study area									
38	No longer in project study area									
39	No longer in project study area									
40	No longer in project study area									
41	No longer in project study area									
42	1057 Donovan Street	Residential								
43	1230 Trenton Street	Residential								
44	1226 Trenton Street	Residential								
45	1220 Trenton Street	Residential								
46	1210 Trenton Street	Residential								
47	1203 Donovan Street	Residential								
48	1207 Donovan Street	Residential				X				X
49	8410 Dallas Avenue South	Spencer Industries								

(X) = Single PIA one property with two business or same site different areas

Summary of Regulatory Database Listing for One Mile Radius Round South Park Bridge

Database	Search Distance (miles)	Within Project Footprint	<1/8 mile	1/8 - 1/4 mile	1/4 - 1/2	1/2 - 1 mile	Total Plotted
	1.00	1	0	0	0	0	1
	1.00	0	0	0	0	0	0
	1.00	0	0	0	0	0	0
	1.00	0	1	2	2	2	5
	1.00	0	0	0	2	1	3
	1.00	0	0	0	1	1	2
	1.00	0	0	0	5	4	9
	1.00	0	0	6	14	128	148
	1.00	0	0	0	10	8	18
	1.00	0	0	2	3	21	26
	1.00	0	0	0	0	1	1
	1.00	0	0	0	0	0	0
	1.00	0	1	3	5	30	39
	1.00	0	1	4	16	69	90
	1.00	0	0	0	0	0	0
	1.00	0	0	0	0	0	0
	1.00	0	0	0	0	0	0
	1.00	0	1	6	20	155	182
	1.00	0	0	0	0	9	9
	1.00	0	0	0	0	1	1
	1.00	0	0	0	0	0	0
	1.00	0	0	0	0	0	0
	1.00	0	0	0	0	5	5
	1.00	0	0	0	0	1	1
	1.00	0	0	0	2	4	6
	1.00	0	0	0	1	1	2
	1.00	0	0	0	3	10	13
	1.00	0	1	5	10	54	70
	1.00	0	3	3	4	28	38
	1.00	0	0	0	3	6	9
	1.00	0	0	0	0	0	0
Coal Gas	1.00	0	0	0	0	0	0
Total Listings		1	6	39	33	72	151

Parcel PIN Number	Shape Color
7883608683	RED
7883607842	RED
7883608370	RED
7883608714	RED
7883608711	RED
7883608668	RED
2185600025	RED
2185600070	RED
2185600080	RED
2185000860	RED
2185000006	RED
2924049098	RED
2924049112	RED
2924049042	RED
0022000005	RED
3324049002	RED
2185000895	YELLOW
2185001045	YELLOW
2185001075	YELLOW
7883607550	YELLOW
7883608629	YELLOW
7883608649	YELLOW
7883608646	YELLOW
7883608614	YELLOW

SITE 1

Initial Site Assessment Checklist

WASHINGTON DEPARTMENT OF TRANSPORTATION INITIAL SITE ASSESSMENT CHECKLIST

Project No.: _____

Work Order: _____

Project Name: SOUTH PARK BRIDGE Region: _____ Route No.: _____

Milepost begin: _____ Milepost end: _____ County Name: KING

Location and Work Description: 7700 16th AVE. S FORMER AUR CO PROPERTY

PROJECT FEATURES (Check "yes" if the answer is maybe)

- | | | |
|--|---|--|
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - New ROW | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Easements | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Excavation |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Relocate utilities | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Dewatering required | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Railroad ROW |

HAZARDOUS WASTE SCREENING

1. What is the project setting? ☐ rural ☐ mixed ☒ urban
- 2a. What is the current land use?
- | | | | |
|--|---|--|--------------------------------------|
| <input checked="" type="checkbox"/> Industrial <u>GAS MAN.</u> | <input type="checkbox"/> Commercial _____ | <input type="checkbox"/> Residential _____ | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Light Industrial _____ | <input type="checkbox"/> Agricultural _____ | <input type="checkbox"/> Undeveloped _____ | |

- 2b. What Is The Past Land Use?
- | | | | |
|--|---|--|--------------------------------------|
| <input checked="" type="checkbox"/> Industrial <u>GAS MAN.</u> | <input type="checkbox"/> Commercial _____ | <input type="checkbox"/> Residential _____ | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Light Industrial _____ | <input type="checkbox"/> Agricultural _____ | <input type="checkbox"/> Undeveloped _____ | |

3. Which of the following records/information sources were used in this assessment?
Describe data in comments or attach copies. LISTED ON WDCR SITE 4 & 5

Federal

- ☒ NPL
☒ CERCLA
☒ RCRA Lists
☐ Permits _____
☐ Other _____

State

- ☒ Ecology Hazardous Site List (LISTED)
☒ Confirmed and Suspected Contaminated Sites Reports
☒ LUST Lists
☒ Other EDR DATA BASE

Local/Regional

- ☐ Air Pollution Control Authority
☐ Fire Departments
☐ City/County Planning
☐ City/County Zoning
☐ Health Department
☐ Other _____

Physical Setting

- ☒ USGS Topographic Map Quad Name _____
☒ Aerial Photographs Date(s) 1934, 47
☐ Soil/Geologic Maps Source _____

Historical Sources

- ☒ Fire Insurance Maps Source SANBORN
☐ Title Records _____
☒ Business/Street Directories Source POUL

Other

- ☐ Region files
☐ Photographs
☐ A previous Initial Site Assessment completed by _____
☐ Other _____

4. Are any known hazardous waste sites adjacent to the project area (approximately 1 mile) which may affect the project?
- ☐ No
☒ Yes - identify and explain BEING PLANT 2 RUN SITE.

NOTE If there is potential for hazardous waste involvement, use the back of this form to draw a sketch map, quad map, or attach photograph(s) with the potential hazardous waste site(s) identified.

VISUAL INSPECTION

1. Was a visual inspection conducted?

☐ No - Why not? _____

☒ Yes - Inspection date 4/2002 - Check below to indicate if any of these features are present in the immediate project area. Indicate whether or not these features appear to present a potential hazardous waste problem. Attach photographs. Describe in comment section.

2a. Physical features

	Potential Problem					
	Y	N	Unk	Y	N	
Underground tanks	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Surface tanks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sumps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Basins	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Containers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Pits/Ponds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Transformers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Chemical storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Service stations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Landfill	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

2b. Contamination

	Potential Problem					
	Y	N	Unk	Y	N	
Surface staining	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Oil sheen	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Odors	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Vegetation damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

INTERVIEWS

1. Were interviews conducted?

☒ No - Why not? _____

☐ Yes - Attach interview memorandum. _____

Name of Person	Date	Telephone Number	Position/Title
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

SITE MAP SKETCH

SME 1

COMMENTS (Add pages if required) NOT TO BE A TAKEN PROPERTY

HIGH POTENTIAL FOR SUBSURFACE ENVIRONMENTAL ISSUES.

LISTED SITE UNDER

LONG HISTORY AS A GAS BOTTLING & MANUFACTURING FACILITY

SURFACE POUNDS (SETTLING BASINS)

LIST OF ATTACHMENTS PHOTO


INITIAL SITE ASSESSMENT CONCLUSION

- | | | |
|--|--|--|
| 1. Does the project have potential hazardous waste involvement? | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes |
| 2. Should the project include any specifications? | <input type="checkbox"/> No | <input type="checkbox"/> Yes - specify _____ |
| 3. Are special acquisition considerations recommended? | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes |
| 4. Based on this Initial Site Assessment, is a Preliminary Site Investigation recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |

J.S. WILBUR - PRES. WILBUR CONSULTING INC.

Name and Title (print)

Signature



Date

9/26/02

SITE 2

Initial Site Assessment Checklist

WASHINGTON DEPARTMENT OF TRANSPORTATION INITIAL SITE ASSESSMENT CHECKLIST

Project Name: SOUTH PAIL BRIDGE Region: _____ Project No.: _____
Milepost begin: _____ Milepost end: _____ Work Order: _____
County Name: KING Route No.: _____
Location and Work Description: 7763 16th AVE. S. BOEING PARKING LOT

PROJECT FEATURES (Check "yes" if the answer is maybe)

☐ Yes ☒ No - New ROW ☐ Yes ☒ No - Easements ☐ Yes ☒ No - Excavation
☐ Yes ☒ No - Relocate utilities ☐ Yes ☒ No - Dewatering required ☐ Yes ☒ No - Railroad ROW

HAZARDOUS WASTE SCREENING

1. What is the project setting? ☐ rural ☐ mixed ☒ urban

2a. What is the current land use?

☐ Industrial _____ ☒ Commercial PARKING ☐ Residential _____ ☐ Other _____
☐ Light Industrial _____ ☐ Agricultural _____ ☐ Undeveloped _____

2b. What Is The Past Land Use?

☐ Industrial _____ ☒ Commercial AIR W SIDE ☐ Residential _____ ☐ Other _____
☐ Light Industrial _____ ☐ Agricultural _____ ☐ Undeveloped _____

3. Which of the following records/information sources were used in this assessment?
Describe data in comments or attach copies.

Federal

☒ NPL
☒ CERCLA
☒ RCRA Lists
☒ Permits _____
☐ Other _____

State

☐ Ecology Hazardous Site List
☒ Confirmed and Suspected Contaminated Sites Reports
☒ LUST Lists
☒ Other EDR DATABASE

Local/Regional

☐ Air Pollution Control Authority
☐ Fire Departments
☐ City/County Planning
☐ City/County Zoning
☐ Health Department
☐ Other _____

Physical Setting

☒ USGS Topographic Map Quad Name _____
☒ Aerial Photographs Date(s) 1939, 47
☐ Soil/Geologic Maps Source _____

Historical Sources

☒ Fire Insurance Maps Source SANBORN
☐ Title Records _____
☒ Business/Street Directories Source POUL

Other

☐ Region files
☐ Photographs
☐ A previous Initial Site Assessment completed by _____
☐ Other _____

4. Are any known hazardous waste sites adjacent to the project area (approximately 1 mile) which may affect the project?
☐ No
☒ Yes - identify and explain BOEING PLANT 2 PLANT S.D.

NOTE If there is potential for hazardous waste involvement, use the back of this form to draw a sketch map, quad map, or attach photograph(s) with the potential hazardous waste site(s) identified.

VISUAL INSPECTION

1. Was a visual inspection conducted?

☐ No - Why not? _____

☒ Yes - Inspection date 4/2002 - Check below to indicate if any of these features are present in the immediate project area. Indicate whether or not these features appear to present a potential hazardous waste problem. Attach photographs. Describe in comment section.

2a. Physical features

	Potential Problem			Potential Problem		
	Y	N	Unk	Y	N	Unk
Underground tanks	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Surface tanks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sumps	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Basins	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Containers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Pits/Ponds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

	Potential Problem			Potential Problem		
	Y	N	Unk	Y	N	Unk
Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transformers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chemical storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Service stations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Landfill	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2b. Contamination

	Potential Problem			Potential Problem		
	Y	N	Unk	Y	N	Unk
Surface staining	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil sheen	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Odors	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

	Potential Problem			Potential Problem		
	Y	N	Unk	Y	N	Unk
Vegetation damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INTERVIEWS

1. Were interviews conducted?

☒ No - Why not? _____

☐ Yes - Attach interview memorandum.

Name of Person	Date	Telephone Number	Position/Title
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

SITE MAP SKETCH

SITE 2

COMMENTS (Add pages if required) NOT A TAKE PRESENT

LIMITED POTENTIAL FOR SUBSURFACE ENVIRONMENTAL ISSUES

LIST OF ATTACHMENTS PHOTO

NONE.


INITIAL SITE ASSESSMENT CONCLUSION

- | | | |
|--|--|--|
| 1. Does the project have potential hazardous waste involvement? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 2. Should the project include any specifications? | <input type="checkbox"/> No | <input type="checkbox"/> Yes - specify _____ |
| 3. Are special acquisition considerations recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 4. Based on this Initial Site Assessment, is a Preliminary Site Investigation recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |

J.S. WILBUR - PRES. WILBUR CONSULTING INC.

Name and Title (print)

Signature



Date

9/26/02

SITE 3

Initial Site Assessment Checklist

WASHINGTON DEPARTMENT OF TRANSPORTATION INITIAL SITE ASSESSMENT CHECKLIST

Project No.: _____

Work Order: _____

Project Name: SOUTH PARK BRIDGE Region: _____ Route No.: _____

Milepost begin: _____ Milepost end: _____ County Name: KING

Location and Work Description: 7745 16th AVE. S. VAGANT LOT

PROJECT FEATURES (Check "yes" if the answer is maybe)

- | | | |
|--|---|--|
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - New ROW | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Easements | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Excavation |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Relocate utilities | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Dewatering required | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - Railroad ROW |

HAZARDOUS WASTE SCREENING

1. What is the project setting? ☐ rural ☐ mixed ☒ urban

2a. What is the current land use?

- | | | | |
|---|--|--|--|
| <input type="checkbox"/> Industrial _____ | <input checked="" type="checkbox"/> Commercial _____ | <input type="checkbox"/> Residential _____ | <input checked="" type="checkbox"/> Other <u>PARKING</u> |
| <input type="checkbox"/> Light Industrial _____ | <input type="checkbox"/> Agricultural _____ | <input type="checkbox"/> Undeveloped _____ | |

2b. What Is The Past Land Use?

- | | | | |
|---|--|--|--------------------------------------|
| <input type="checkbox"/> Industrial _____ | <input checked="" type="checkbox"/> Commercial <u>BANK</u> | <input type="checkbox"/> Residential _____ | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Light Industrial _____ | <input type="checkbox"/> Agricultural _____ | <input type="checkbox"/> Undeveloped _____ | |

3. Which of the following records/information sources were used in this assessment?

Describe data in comments or attach copies. SITE NOT LISTED ON AGENCY SITE LIST

Federal

- ☒ NPL
☒ CERCLA
☒ RCRA Lists
☐ Permits _____
☐ Other _____

State

- ☒ Ecology Hazardous Site List
☒ Confirmed and Suspected Contaminated Sites Reports
☒ LUST Lists
☒ Other EDR DAMBARK

Local/Regional

- ☐ Air Pollution Control Authority
☐ Fire Departments
☐ City/County Planning
☐ City/County Zoning
☐ Health Department
☐ Other _____

Physical Setting

- ☒ USGS Topographic Map Quad Name _____
☒ Aerial Photographs Date(s) 1939, 47
☐ Soil/Geologic Maps Source _____

Historical Sources

- ☒ Fire Insurance Maps Source SANBORN
☐ Title Records _____
☒ Business/Street Directories Source PALM

Other

- ☐ Region files
☐ Photographs
☐ A previous Initial Site Assessment completed by _____
☐ Other _____

4. Are any known hazardous waste sites adjacent to the project area (approximately 1 mile) which may affect the project?

- ☐ No
☒ Yes - identify and explain BEARING BORING PLANT

NOTE If there is potential for hazardous waste involvement, use the back of this form to draw a sketch map, quad map, or attach photograph(s) with the potential hazardous waste site(s) identified.

VISUAL INSPECTION

1. Was a visual inspection conducted?

☐ No - Why not? _____

☒ Yes - Inspection date 4/2002 - Check below to indicate if any of these features are present in the immediate project area. Indicate whether or not these features appear to present a potential hazardous waste problem. Attach photographs. Describe in comment section.

2a. Physical features

	Potential Problem					
	Y	N	Unk	Y	N	
Underground tanks	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Surface tanks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Sumps	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Basins	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Containers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Pits/Ponds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Transformers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Chemical storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Service stations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Landfill	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

2b. Contamination

	Potential Problem					
	Y	N	Unk	Y	N	
Surface staining	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Oil sheen	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Odors	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Vegetation damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

INTERVIEWS

1. Were interviews conducted?

☒ No - Why not? _____

☐ Yes - Attach interview memorandum. _____

Name of Person

Date

Telephone Number

Position/Title

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

SITE MAP SKETCH

SITE 3

COMMENTS (Add pages if required) NOT A TAKE PROPERTY

LIMITED POTENTIAL FOR SUBSURFACE ENVIRONMENTAL ISSUE

LIST OF ATTACHMENTS PHOTO

NONE

INITIAL SITE ASSESSMENT CONCLUSION

- | | | |
|--|--|--|
| 1. Does the project have potential hazardous waste involvement? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 2. Should the project include any specifications? | <input type="checkbox"/> No | <input type="checkbox"/> Yes - specify _____ |
| 3. Are special acquisition considerations recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 4. Based on this Initial Site Assessment, is a Preliminary Site Investigation recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |

JS Wilbur - PRES WILBUR CONSULTING INC.
Name and Title (print)

JSW
Signature

9/26/02
Date

SITE 4 - VACANT LOT
Initial Site Assessment Checklist

**WASHINGTON DEPARTMENT OF TRANSPORTATION
INITIAL SITE ASSESSMENT CHECKLIST**

Project Name: SOUTH PARK BRIDGE Region: _____ Project No.: _____
Milepost begin: _____ Milepost end: _____ Work Order: _____
County Name: KING
Location and Work Description: 7747 16th AVE. S

PROJECT FEATURES (Check "yes" if the answer is maybe)

☐ Yes ☒ No - New ROW ☐ Yes ☒ No - Easements ☐ Yes ☒ No - Excavation
☐ Yes ☒ No - Relocate utilities ☐ Yes ☒ No - Dewatering required ☐ Yes ☒ No - Railroad ROW

HAZARDOUS WASTE SCREENING

1. What is the project setting? ☐ rural ☐ mixed ☒ urban
- 2a. What is the current land use?
☐ Industrial _____ ☒ Commercial APR 26 ☐ Residential _____ ☒ Other PARKING LOT
☐ Light Industrial _____ ☐ Agricultural _____ ☐ Undeveloped _____
- 2b. What Is The Past Land Use?
☐ Industrial _____ ☒ Commercial 1940s ☐ Residential _____ ☐ Other _____
☐ Light Industrial _____ ☐ Agricultural _____ ☐ Undeveloped _____
3. Which of the following records/information sources were used in this assessment?
Describe data in comments or attach copies.
- | Federal | State | Local/Regional |
|--|---|--|
| <input type="checkbox"/> NPL | <input type="checkbox"/> Ecology Hazardous Site List | <input type="checkbox"/> Air Pollution Control Authority |
| <input type="checkbox"/> CERCLA | <input type="checkbox"/> Confirmed and Suspected Contaminated Sites Reports | <input type="checkbox"/> Fire Departments |
| <input type="checkbox"/> RCRA Lists | <input type="checkbox"/> LUST Lists | <input checked="" type="checkbox"/> City/County Planning |
| <input type="checkbox"/> Permits _____ | <input type="checkbox"/> Other _____ | <input type="checkbox"/> City/County Zoning |
| <input type="checkbox"/> Other _____ | | <input type="checkbox"/> Health Department |
| | | <input type="checkbox"/> Other _____ |
- Physical Setting**
☐ USGS Topographic Map Quad Name _____
☒ Aerial Photographs Date(s) 1936
☐ Soil/Geologic Maps Source _____
- Historical Sources**
☒ Fire Insurance Maps Source _____
☐ Title Records _____
☒ Business/Street Directories Source POLK
- Other**
☐ Region files
☐ Photographs
☐ A previous Initial Site Assessment completed by _____
☐ Other _____
4. Are any known hazardous waste sites adjacent to the project area (approximately 1 mile) which may affect the project?
☐ No
☒ Yes - identify and explain

NOTE If there is potential for hazardous waste involvement, use the back of this form to draw a sketch map, quad map, or attach photograph(s) with the potential hazardous waste site(s) identified.

VISUAL INSPECTION

1. Was a visual inspection conducted?

☐ No – Why not? _____

☒ Yes – Inspection date _____ - Check below to indicate if any of these features are present in the immediate project area. Indicate whether or not these features appear to present a potential hazardous waste problem. Attach photographs. Describe in comment section.

2a. Physical features

	Potential Problem					
	Y	N	Unk	Y	N	
Underground tanks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Surface tanks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Sumps	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Basins	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Containers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Pits/Ponds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Transformers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Chemical storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Service stations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Landfill	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

2b. Contamination

	Potential Problem					
	Y	N	Unk	Y	N	
Surface staining	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Oil sheen	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Odors	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Potential Problem					
	Y	N	Unk	Y	N	
Vegetation damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

INTERVIEWS

1. Were interviews conducted?

☒ No – Why not? _____

☐ Yes – Attach interview memorandum. _____

Name of Person	Date	Telephone Number	Position/Title
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

SITE MAP SKETCH

SITE

COMMENTS (Add pages if required)

LIMITED POTENTIAL FOR SUBSURFACE ENVIRONMENTAL ISSUES

LIST OF ATTACHMENTS PHOTO

INITIAL SITE ASSESSMENT CONCLUSION

- | | | |
|--|--|--|
| 1. Does the project have potential hazardous waste involvement? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 2. Should the project include any specifications? | <input type="checkbox"/> No | <input type="checkbox"/> Yes - specify _____ |
| 3. Are special acquisition considerations recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |
| 4. Based on this Initial Site Assessment, is a Preliminary Site Investigation recommended? | <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes |

J.S. WILBUR - PRES. WILBUR CONSULTING, INC.
Name and Title (print)

JSW
Signature

2/26/02
Date

SITE 5

Initial Site Assessment Checklist

WASHINGTON DEPARTMENT OF TRANSPORTATION INITIAL SITE ASSESSMENT CHECKLIST

Project No.: _____

Work Order: _____

Project Name: SOUTH PARK BRIDGE Region: _____ Route No.: _____

Milepost begin: _____ Milepost end: _____ County Name: KING

Location and Work Description: 7749 16th AVE. S. (NORTH CAMPUS AREA PLANT 2)

PROJECT FEATURES (Check "yes" if the answer is maybe)

- | | | |
|--|---|--|
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No - New ROW | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No - Easements | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No - Excavation |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No - Relocate utilities | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No - Dewatering required | <input type="checkbox"/> Yes <input type="checkbox"/> No - Railroad ROW |

HAZARDOUS WASTE SCREENING

1. What is the project setting? ☐ rural ☐ mixed ☒ urban

2a. What is the current land use?

- | | | | |
|---|---|--|--------------------------------------|
| <input checked="" type="checkbox"/> Industrial <u>AIRCRAFT MAN.</u> | <input type="checkbox"/> Commercial _____ | <input type="checkbox"/> Residential _____ | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Light Industrial _____ | <input type="checkbox"/> Agricultural _____ | <input type="checkbox"/> Undeveloped _____ | |

2b. What Is The Past Land Use?

- | | | | |
|--|--|--|--------------------------------------|
| <input checked="" type="checkbox"/> Industrial _____ | <input type="checkbox"/> Commercial _____ | <input type="checkbox"/> Residential _____ | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Light Industrial _____ | <input checked="" type="checkbox"/> Agricultural <u>1936</u> | <input type="checkbox"/> Undeveloped _____ | |

3. Which of the following records/information sources were used in this assessment?

Describe data in comments or attach copies.

Federal

- ☒ NPL
☐ CERCLA
☒ RCRA Lists
☐ Permits _____
☐ Other _____

State

- ☒ Ecology Hazardous Site List
☐ Confirmed and Suspected Contaminated Sites Reports
☒ LUST Lists
☒ Other EDR DATABASE

Local/Regional

- ☒ Air Pollution Control Authority
☐ Fire Departments
☒ City/County Planning
☐ City/County Zoning
☐ Health Department
☐ Other _____

Physical Setting

- ☒ USGS Topographic Map Quad Name _____
☒ Aerial Photographs Date(s) 1936, 1947,
☐ Soil/Geologic Maps Source _____

Historical Sources

- ☒ Fire Insurance Maps Source _____
☐ Title Records _____
☐ Business/Street Directories Source _____

Other

- ☐ Region files
☐ Photographs
☐ A previous Initial Site Assessment completed by _____
☐ Other _____

4. Are any known hazardous waste sites adjacent to the project area (approximately 1 mile) which may affect the project?

- ☐ No
☒ Yes - identify and explain BOEING PLANT 2 RCRA, LOWER DYNAMISB WATERWAY NPL SITE

NOTE If there is potential for hazardous waste involvement, use the back of this form to draw a sketch map, quad map, or attach photograph(s) with the potential hazardous waste site(s) identified.